

REF:CS1/SCD24080404/Eqp3 (SLJ 223D)

Special Instruction:

ASSIGNMENT (Office)

From (Person): RALF of SCDF Date/Time: 23/08/2024

Estimated Cost: _____ Bill to: _____

L/SUM: 10,053.69 / REPAIR : 5 DAYS

Third Parties:

Claimant:

Surveyor: AIG Asia Pacific Insurance Pte. L

Workshop: CYCLE & CARRIAGE INDUSTRIES PL

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLJ 223D

Insured: GBM 1086D

at Workshop m/s CYCLE & CARRIAGE INDUSTRIES PL

of 188 PANDAN LOOP (MERCEDES-BENZ)

Policy No: _____ Claim No: 2023 - 99

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/09/2023
(Client's Record)

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red \$____/____%; Original ____ days)

Date/Time: 26/08/24 Submit Final Fig \$9465.69, 4 days (Red \$ 588 / 6 %; Original 5 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 26/08/24 File Pass to Typist

2) Date/Time

File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time

File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time

File Return to