

ASS. REC. BY: NA2

REF:

CS/CTI24080412/Nnh3e2

CTI

L/S

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLN 5752 P

at Workshop m/s VINS AUTOMOTIVE

of 160 SW MING DRIVE #08-09

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: ~~85K~~ 94K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 5752 P Yr Regn: 9 MAY 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ E200 6.0 1,950

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: NA (battery not full) T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2130042A185927

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 225/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TRIANGLE

Front Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 22/8/2024 D.O.I. 26/8/2024

Survey held at VINS AUTO

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or engine compartment

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COE Rebate \$ 46,479.00

Repair Limit \$ 36,000

vehicle badly burnt - mechanical to repair - recommend total loss

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS - SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$ _____)