ASS. REC. BY:	CS/ICS24080426/Kvp3
Kenneth	SCICAIMENIE
From: Date: Estimated Cost: OD/ITP/WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No: at Workshop m/s of Insured: Policy No. MPC24B00054800 Claims No. DMPC2401073H/CT Sum Insured: Excess: 1236 (Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of Inspection. Bal. or Market Value: 1/2/ IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 3 days Res.: Yes or No Lum Sum: / B. / % 3 Val.: Yes or No CA / REV / REP. / 24 HRS	Veh No: SDS 8/10 R Yr Regn: 04, 19 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailler or A)
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
A STATE OF THE STA	anected due to collision.
418 & 6293-00 Cale (red)	1290, 17%)
Coving (led	1230, 1770)
'I Floring	ys Of Repair: 3 survey No. of Trip: Survey Fee:
Add Fee:	: Site Insp (\$
Report Format :	: Interview (\$). Findow
Lump Sum / I.B.I: (S	Tech Invs (\$) Others
1	Weekend (\$
* *	10.74

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

WD)
php)

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE. The information contained herein is correct as at 16 Aug 2024

SO03248GM002-01 / OPTIMA WERKZ PTE LTD ENTRY DATE & TIME: 16/08/2024 16:48 (SGT) SUBMITTED BY: MOHAMED NASHIK VERSION: 2 (21/08/2024 12:25 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. 5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

16/08/2024 16:48 (SGT) Both Policyholder and Actual Driver 16/08/2024 14:11 (SGT) 14 Ang Mo Kio Central 3, Singapore 567747 SLIP ROAD OF AMK AVE 8 & AME AVE 5, SINGAPORE Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SDS8110R

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No

Email Address

Mobile Phone No Alternative Phone No No SHEE WOON HWEE (XU WENHUI) SXXXX372J LEONARD.SHEE@GMAIL.COM

(Phone) +65-93683761

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Vehicle Fuel

First Regisration Date

Chassis no

Effective Date/Time of Ownership

Toyota

Rav4

Private use

Yes

Private car

Auto

1987

JTMY43FV80D502940

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

ECICS Limited MPC24B00054800

DRIVER



SHEE HUI JIN, VANESSA Name of Driver SXXXX573D NRIC No 20/09/1996 Date Of Birth Occupation Indoor 22/10/2015 **Driving Pass Date** Driving License Pass Class **3A** Valid **Driving License Validity** 8 YEARS AND 10 MONTHS Driving experience Gender Female (Phone) +65-90105098 Mobile Number Alt. Phone Number VANESSASHEE@HOTMAIL.COM **Email Address** BLK 511 YIO CHU KANG ROAD Address Address complement #04-21 S787066 Postcode Is the driver the policyholder? No If No. Relationship of the Driver with the Insured Child Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name NH LAY HWEE Gender Female **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S)

Yes

No

Are accident photos available for attachment?

Was there any video captured by Car Camera?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBM6431H
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	LOH SU LIN IRENE
NRIC No	SXXXX989G
Contact Number	(Phone) +65-84683955
Address	-
Address complement	=
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre

Sketch Plan

ANG MO KIO AVE S

16 Au	ng at 2.11 pv	a mon	driving at	ord and	0 1 1 1	
CONTRACTOR OF THE PARTY OF THE	nstances of the According of 2.11 Pure to Ming Ma	KLO AVE	5 the	COU IN	KNNH did	1001
TANKING .	0 1	tempelead	curta the	v veav.		
CLAN ON.	D63006 /	150000 10100				
		and the second s				

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Optima Werkz Pte Ltd (Co.Reg.No:201212455W) 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047 Tel: 6481 1522

INSURER:

ECICS Limited (HQ)

PARTICULARS OF	CLAIM
----------------	-------

Claim Type: Policy No:

OD (OWN DAMAGE)

MPC24B00054800

SDS8110R

Vehicle Reg. No.: Driver Age/Info:

TP Injury Involved? Insured/Claimant:

NO

SHEE HUI JIN, VANESSA

Make/Model:

TOYOTA RAV4, 2.0 PREMIUM SUV

(2WD) (A)

Vehicle Colour:

RED

Engine No:

M20AV028469

80357 KM Odometer:

Paint Type:

Total Loss?

Est. Duration of Repair

(day)

NO

8 3. day,

Ref. No:

Date of Loss:

Driveable?

Party At Fault:

UNKNOWN

16/08/2024

Third Party Involved? YES

30/04/2019 Vehicle Reg. Date:

Chassis No:

JTMY43FV80D502940

Not Notherstal Acrony B4 paint \$8293.00 Ex & 1250h

Present Location:

OPTIMA WERKZ PTE LTD (HQ)

		Amount
COST OF CLAIMS		5,478.00
Parts		305.00
Miscellaneous Items		1,800.00
Labour		0.00
Paintwork Labour		0.00
Towing	Gross Total (S\$)	7,583.00
	+ GST 9.00% (S\$)	682.47
	Nett Amount (S\$)	8,265.47

This claim is handled by: LOONG GHIEN YEE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 23 Aug 2024)

Parts:

M1-SUV

TOYOTA RAV4 2.0 PREMIUM SUV (2WD) (A) (Catalogue:Merimen Singapore 1.0)

Labour:

(Price-denominated Standard List) Repairer's

Print Code: (Unsubmitted, no print-code for SDS8110R)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Esti	mates	on	Parts
------	-------	----	-------

No.	Qty	Part No.	Particulars	%	Disc	%Depr	1	Amount	
1	1		Bumper, front	cm	0.00	0.00		*260.00 F	_
2	1		Fender LH, front	macm			*4	000 00 5	-
3	1		Headlamp LH	Mi	0.00	0.00		,800.00 F	1
4	1		Radiator grille	" scus	0.00	0.00		*240.00 F	-
5	1		Radiator grille bracket	cm	0.00	0.00		*220.00 F	
6	1		Radiator grille emblem		0.00	0.00		*400.00 F	
7	1		*Radiator Grille Lower No.2	cm	0.00	0.00		*170.00 F	
8	1		*Front Bumper Guard		0.00	0.00		*260.00 F	
9	1		*Front Bumper Outer Moulding	nd	0.00	0.00		*280.00 F	
10	1		*Front Radar Sensor	no	0.00	0.00		*850.00 F	
11	1		*Front LH Bumper Retainer		0.00	0.00	DM	10.001	
12	1		*Front Bumper Energy Absorber	cm		0.00		*70.00 F	
13	1		*Front Bumper Reinforcement	Bu	0.00	0.00		*300.00 F	7
14	1		*Front Bumper Licence Plate Mounting Bracket		0.00	0.00	nd	*60.00 F	-
F=Fr	anchise	e part.		grand.com					
				b Total (S\$)			4	1,980.00	
			+ Margin on L,N Items 1	10.00% (S\$)				498.00	
			Tota	I Parts (S\$)			!	5,478.00	
				400000000					

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars			A	mount	
Mis 1	cella 1	reous Items Front Bumper Clips		M	50.00 ×
2	1	Front Bumper Lower Guard Clips		NA	50.00 X
3	1	Front Fender Liner Clips Front Fender Outer Garnish Clips	Nr.	201N 855N	50.00 7
5	1	Front Licence Plate Number with Frame			55.00
6	0 0	y.	ra	50.00	
			Sub Total (S\$)		305.00
			grander to	Management of the Parket of th	

Es No	timates on Labour Particulars	Lab.Type	,	Amount	
<u>Lab</u> 1	our Items To Straighten and Panel Beat of Accident Affected Areas To Furnish Material, Supply and Spray Paint at Front Bumper, Front LH Fender Panel, Etc	New New	200	250 600.00 700.00	
3	To Readjust and Realign Headlamp Aim To Recalibrate and Reset Radar Sensor	New New		100.00	
5	To Check Wiring and Electrical System	New	201	100.00	
	Gross Labou	ır Cost (S\$)		1,800.00	

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: