

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Endoration Internationals Dec Eymouto En Automobile					
Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL INSURANCE (S) PL		Ref:	CS/AGI24080434/Uvp3	
	(BUDGET DIRECT I 190 CLEMENCEAU	NSURANCE) AVENUE #03-01	Date:	27/08/2024	
		PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMU 7493A	Veh. Inspected	SMU 7658S	
	Policy No.	P10434893R03	Coverage	0	
	Claim No.	C10031327 / CY	Excess	\$0.00	
	Assign From	CALEEN YIT	Assign Date	26/08/2024	
2. Vehicle Details					
	Make & Model	HYUNDAI AVANTE GLS (A)	C.C	1591	
	Engine No.	G4FGLU122281	Year of Reg.	28/08/2020	
	Chassis No.	KMHD841CMLU100254	Colour	RED	
	Odometer	134356 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM	•		
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55R16	YOKOHAMA	6	
	L/H Front Tyre	205/55R16	YOKOHAMA	6	
	R/H Rear Tyre	205/55R16	YOKOHAMA	6	
	L/H Rear Tyre	205/55R16	YOKOHAMA	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	25/08/2024	Inspection Date	26/08/2024	
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
FORMATED MODIMAL DEPLOD FOR DEPAIR & Working Days					

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days