

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estn: \_\_\_\_\_  
 OD / TP RES / OD RES / EVA / INV / MV  
 To In: \_\_\_\_\_ Vehicle No: \_\_\_\_\_  
 at: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy: \_\_\_\_\_  
 Claims: \_\_\_\_\_  
 Sum: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repair: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: FBR1848X Yr Regn: 2020 March.  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Yamaha XMAX 300cc 292  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MH 3SH 0847LK00  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 120/70 R15  
 R: 140/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 0 mm L/Bal. \_\_\_\_\_ mm  
 D.O.A. \_\_\_\_\_ D.O.I. 27/08/24  
 Survey held at MS Car.

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                   |
|-------------|----------------------------------------|
|             | <u>TP INC</u>                          |
|             | <u>COE Expiry</u>                      |
|             | <u>Estimate given during : Yes ( )</u> |
|             | <u>1st Survey : No (✓)</u>             |
|             | <u>MV :</u>                            |
|             | <u>PV :</u>                            |
|             | <u>Nett :</u>                          |
|             | <u>0221.</u>                           |

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Inve (\$ \_\_\_\_\_)

Report Format: \_\_\_\_\_

Report Form: \_\_\_\_\_