

ASS. REC. BY:

REF: SMR / CS/SMR24080462/Kvp3Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **SMB 5077C**

Policy No. _____

Claims No. **BUS/08/24/5037**

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 02 days

Res.: Yes or No

Lum Sum: 1.51 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: ET 8138UYr Regn: 01, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

WagonMake: Bmw216dc.c. 1496Colour: M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 180684

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 2E 320 40P 837010Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / R/Rim or

Tyre Size: F: _____

R: _____

205/35R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 21/8/24D.O.A. 24/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt d/s door mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/10 @ 2247.75 Carbur (red 50, 2%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

: Fuel

: Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 522J

Vehicle Details

Vehicle No.: ET8138U
Vehicle to be Exported: Yes
Intended Deregistration Date: 22 Aug 2024
Vehicle Make: B.M.W.
Vehicle Model: 216D GRAN TOURER LED NAV 7 SEATER
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: 32379421B37C15A
Chassis No.: WBA2E32040P837010
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$31,447.00
Original Registration Date: 26 Jan 2016
First Registration Date: 26 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$26,026.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Jan 2026
PARF Rebate Amount: \$14,314.00

Intended COE Rebate Details

COE Expiry Date: 25 Jan 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$51,000.00
COE Rebate Amount: \$7,266.00
Total Rebate Amount: \$21,580.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 22 Aug 2024

OK



CERTIFICATE OF INSURANCE

AUTOPLUS PRIMATE VEHICLE

Name of Policyholder : Tan Me Me
Period of Insurance : 26 Jan 2024 To 26 Jan 2025
Engine/Motor No. : 32379421B37C15A
Chassis No. : WBA2E32640P837010

Vehicle No. : ET8138U
Policy No. : 2100498827-07
Endorsement No. :
Issued Date : 22 Jan 2024 16:48

ABOUT THE COVER

Make/Model : BMW 216D Gran Tourer
Engine Capacity/Tonnage : 1,496.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$553,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (as defined) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Mileage Condition : Unlimited Mileage
Limitation as to use* :

Use only for social, domestic and pleasure purposes or for the Policyholder's business.
This Policy does not cover a vehicle or goods, driving tuition, driving test, racing, motorcycling, reliability test or pace-making, the carriage of goods other than sundries in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1000hr - 1000hr Option 1

* Exclusions referred to in Section 6 of the Motor Vehicle (Third Party Risks and Compensation) Act 1997, Section 21 of the Road Transport Act 1997 (Malaysia) and Road Transport (Passenger) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$300 Theft - \$0 Flood Cover - \$250

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Total Excess : \$300 (Own Damage), \$250 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to this Vehicle must be carried out by one of our Act endorsed Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore. You have the option of having the accident repairs carried out at the Cash Agent's workshop.
For other Approved Reporting Centres/Authorised Repairers please contact our 24-hour accident or emergency hotline at +65 6259 6330. Alternatively, You may refer to AIG web site www.aig.sg

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicle (Third Party Risks and Compensation) Act 1997, Part IV of the Road Transport Act 1997 (Malaysia), Road Transport (Liability) Act 2019 and Motor Vehicle (Third Party Risks) Rules, 1999 (Malaysia).

0000084000
DIRECT CLIENTS 014 95

AIG Asia Pacific Insurance Pte. Ltd.
This computer generated document does not require a signature.

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

PRODUCED BY AIG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	22/08/2024 17:25 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	21/08/2024 15:20 (SGT)
Exact Location of Accident	Choa Chu Kang Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	ET8138U
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Tan Me Me
NRIC No	SXXXX522J
Email Address	mimitan6166@gmail.com
Mobile Phone No	(Phone) +65-98567708
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	216d
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2100498827-07

DRIVER

Name of Driver	Tan Me Me
NRIC No	SXXXX522J
Date Of Birth	26/11/1966
Occupation	Outdoor
Driving Pass Date	26/04/1988
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	36 YEARS AND 4 MONTHS
Gender	Female
Mobile Number	(Phone) +65-98567708
Alt. Phone Number	-
Email Address	mimitan6166@gmail.com
Address	Blk 116A Canberra Crescent #10-302
Address complement	-
Postcode	751116
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMB5077G
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	Kalaichelvan A/L Kannan
Contact Number	(Phone) +65-88573559
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. This report contains the details of the accident to assist in the police process.
2. This form must be completed by the Police Officer or the Accident Officer.
3. Information provided must be an accurate response to the questions. Any willful misrepresentation or withholding of material information may constitute an offence under the Road Traffic Act.
4. The completion and signing of this form by the driver constitutes an admission of liability. It is the part of the accident compensation process.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for storing and that also is available upon application by interested parties.
7. By the completion of this report to the insurers, you hereby consent to the storing of this report at the centre and to allow the report being made available to others.

Consent under the Personal Data Protection Act (PDPA)

I understand and acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data and any information set out in this form and any other personal information provided by me or disclosed by my insurer collected for the "Personal Information" and disclose and transfer such Personal Information to insurers and have insured vehicles involved in this accident (or insurers) who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers". The Insurers/Lawyers/Law firms, the Monetary Authority of Singapore and any relevant government authority (Ministry) shall use the data, for the purposes of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims, and any necessary investigations relating to my claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out investigations with my insurer or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, involving reports or notices to me) which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external court or a website that I have access to;
 - (v) complying with applicable laws, administrative regulations, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All Insurers who have insured vehicles involved in this accident and the Insurers/Lawyers/Law firms, may be permitted to collect, use, disclose and/or process my Personal Information for the purpose of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be outside of Singapore, for one or more of the above Purposes.

Police Officer's Signature (Date & Time)
22 AUG 2024

Accident Driver's Signature (If driver is not the policyholder) (Date & Time)

Witnessed by Reporting Centre Personnel (Name and NRIC ID No.)
Jenny Lim

Sketch Plan

Sketch Plan

Choa Chu Kang Rd

X - ET 8138 U

B - SMB 5577 G

Lamp post (10)

Road closed construction work

Jun dim

Nursing Home

Describe Circumstances of the Accident

I was on my way home from Buloh Batik around 3:20 pm on 21/8/24. When I was on Chua Chu Kang Rd, round lamp post 10, there was road works going on and the extreme left lane was closed. There was heavy traffic too. I was at the centre lane and not moving, stationed, probably was red light or something. All cars were stopped. Suddenly I felt that I ~~was~~ my car shaked. For a moment I was shocked. Then I realized a SMART double deck bus hit my car. He was trying his to squeezed through on my right. My right side mirror was badly damaged by the hit. The cover fell on the road. I managed to pick it up after.

The SMART bus is bus number 67, with car plate no. CNB5077G. Driver is Mr Kalaiichelvan A/L Kannan. His mobile number is 88573559. He admitted he was at fault. ^{was} I was wondering why the bus _{was} on the extreme right lane.

He did apologise to me. I was lucky that I was not hurt and only right side mirror was damaged. Then again, is the time and trouble that I need to do all the claiming stuffs. Waste my time.

There was a lot of traffic controller at the time of accident and one gentleman came to me and told me to take down the lamp post number.

Declaration

I/We declare the foregoing particulars are true and correct.

Reported Person's Signature & Date

Witness (Driver's Signature if driver is not the police holder)
Name & Time

Witness's (Reporting Centre) Signature

Name as PNR CARD read: Jenny Lim

22 AUG 2024

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0035578
Tan Me Me

Page : 1 of 1
Your ref. : TP-SMB 5077G
Job No. : 74669
Our ref. : 24.08.31
Payment :
Date : 10/9/2024

Attn :

Vehicle No : ET 8138U
Vehicle Model : BMW 216D
Accident on : 21/8/2024

NOT WITHIN
Repair By pain
\$ 2247.75 2 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts-Nett item:					
1.00	Pc	Front wing mirror upper cover RH	360.00	10.00 CM	324.00 ✓
1.00	Pc	Front wing mirror lower cover RH	180.00	10.00 DA	162.00 ✓
1.00	Pc	Front wing mirror signal lamp RH	260.00	10.00 CM	234.00 ✓
1.00	Pc	Front wing mirror frame RH	1,237.50	10.00 DA	1,113.75 ✓
1.00	Pc	Front wing mirror base housing cover RH	260.00	10.00 MYCM	234.00 ✓
Labour & Misc:					
1.00		To dismantle+renew above parts	150.00		150.00 100% ✓
1.00		To spray paint	80.00		80.00 ✓

Sub-Total 2,297.75
GST 9.00% 206.80
Total S\$ 2,504.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."