

REF:

CS/11124080463/Aqp3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum ENSU: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

79 111

COE Expiry

Estimate given during : Yes (✓)
1st Survey : No (✓)

MV :

PV :

Nett :

069W

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2)

Report Format :

1. Report Form / 2. P. 10

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)
☐ : _____

Site Insp (\$)

Interview (\$)

Tech. Inve (\$)

Survey Fee:

Transportation:

3 + RS \$1

Photos

Others

Veh No: SL6 266XYr Regn: 2016/SeptType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel HybridC.D. 1496Colour: Bronze

A/C: Insured / Std / NI / NA

Sp. Reading: 297188

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU31210064Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R16R: 215/65R16

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 27/08/24

Survey held at

A-TecDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.