

**CVI INVOLVING FAST  
RESPONSE VEHICLE (FRV)  
MID34591 AND HANGING  
LOUVRE GRILL AT NATIONAL  
ARCHIVES SINGAPORE ON 03  
AUG 2024 AT ABOUT 0900HRS**




Figure A-1: MID34591 Arriving at National Archives Singapore Carpark




Figure A-2: MID34591 Performing a 3 Point Turn at the Empty Carpark




Figure A-3: MID34591 Reversing towards the Sheltered Parking Lots




Figure A-4: MID34591 came into contact with the Overhead Louvre Grill



Figure B-1: Front View of MID34591



Figure B-2: Rear View of MID34591



Figure B-3: Left Side View of MID34591





Figure B-4: Right Side View of MID34591




Figure B-5: Zoomed-in View of Damaged Area on MID34591

Damage assessment: MID34591 with dented rear right cabin with superficial paint scratches

## STATEMENT OF DRIVER/WITNESS

STATEMENT OF		GOH WEI ERN		ALIASES	
NRIC NO.	██████	AGE	22	MALE/FEMALE	MALE
EMPLOYMENT	NSF	DRIVING LICENSE NO	SAF/TPT/N/00757/25	NATIONALITY	SINGAPOREAN
DIALECT	HOKSIEN	LANGUAGE SPOKEN	ENGLISH	TEL NO	██████
ADDRESS					
INTERPRETED BY		RANK	TIME	DATE	SIGN
RECORDED BY		RANK	TIME	DATE	SIGN

On 03082024 Saturday at about 0900 hours, I, (FC) Goh Wei Ern, DV 15C9I 1SR Coy, drove FRV vehicle number 3F591M10 into national archives private carpark for national day deployment. As I wanted to do a 3 point turn to park my vehicle into the designated parking spot, I came down to do my reversing drill and identified the pillar as the main hazard for my vehicle. I asked my vehicle commander 3SG TAN JUN XI to get off the vehicle and keep a lookout for the pillar while I execute the 3 point turn. I was focused on my right side view mirror when reversing to look out for the pillar and continued to reverse once I made sure that the vehicle had cleared the pillar. I immediately stepped on the brake as I heard a shout from my vehicle commander 3SG TAN JUN XI who was on the ground keeping a lookout for the pillar. I was told that my vehicle had come into contact with an aluminium grill. I proceeded to move my vehicle forward to clear the aluminium grill.

DATE	SIGNATURE OF DRIVER/WITNESS
03/08/2024	

All statements and further statements are to be timed and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.  
Statements of witness must be signed by the Witness.

SAF 1201

### Figure C-1: Statement of Driver

**SINGAPORE ARMED FORCES**  
**STATEMENT OF DRIVER/WITNESS**

STATEMENT OF	TAN JUN YI			ALIASES	
NRIC NO.	T 911F	AGE	20	MALE/FEMALE	MALE
EMPLOYMENT	NF	DRIVING LICENSE NO	-	NATIONALITY	SINGAPOREAN
DIALECT		LANGUAGE SPOKEN		TEL NO	
ADDRESS					
INTERPRETED BY		RANK		TIME	DATE
RECORDED BY		RANK		TIME	DATE
<p>On 030824 at about 1100, I 350 Tan Jun Yi the vehicle remainder of 0303 34591 arrived with my vehicle at the private carpark of national archives. During a 2-pool turn, IFC 0004 Wli for the 0V of the vehicle noticed a potential pillar hazard (2nd pillar (from the back) or the right of the vehicle and requested for me to dismount and ensure he does not hit it. I dismounted and stood on the right of the vehicle as it reversed and was prepared to sound off if it came near the pillar, my sole focus was on the pillar, after the vehicle cleared the pillar, I heard a sound and looked the top of a lot and I immediately sounded off to my 0V to stop and move forward to clear the steel gate.</p>					
<p>DATE 03/08/24 SIGNATURE OF DRIVER/WITNESS <i>W</i></p>					

All statements and further statements are to timed and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.

Statements of witness must be signed by the Witness.

SAF 1201

Figure C-2: Statement of VC





**SINGAPORE  
POLICE FORCE**



T/20240803/7028

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20240803/7028

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 03/08/2024 13:43		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: Goh Wei Ern			Address: [REDACTED]		
ID Type / ID No.: NRIC NO / [REDACTED]			Contact No.: Home/Office: [REDACTED] Mobile: [REDACTED]		
Nationality: SINGAPORE CITIZEN			Email: [REDACTED]		
Sex: Male	Age: 22	Date of Birth: 05/02/2002	Type of Informant: Driver of SAF MID 34591		
Race: Chinese			Language: English		
Occupation: National Service Full Time			Driving Licence Information: Class: [REDACTED] Date of Expiry: [REDACTED]		

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 03/08/2024 09:00	Type of Location: Car Park
Location:  CANNING RISE				
Weather: Clear		Road Surface: Dry		
Traffic Flow:		Traffic Control:		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
MID34591	Motor car	MERCEDES BENZ	SPRINTER	White	Slightly Damaged	1

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Figure D-1

**SINGAPORE  
POLICE FORCE**

T/20240803/7028

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20240803/7028

## CONTINUATION OF REPORT

Driver of SAF MID 34591				
Name	Goh Wei Ern		ID No.	[REDACTED]
Related Vehicle	NIL		Contact No.	[REDACTED]
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL		Degree of Injury	NIL

**Brief Details.**

Moving Vehicle against splash guard of the building beside the open carpark

Figure D-2



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20240803/7028

3 of 3

Report No. T/20240803/7028

CONTINUATION OF REPORT

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
LOW MENG FATT  
Contact No.: 97577566

NP168

Signature Of Informant:  
The identity of the person making this report has been  
authenticated by Singpass. No signature is required.

Date/Time:  
03/08/2024 13:43

Classification Of Case:

Figure D-3