



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24080477/Uqh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	23/09/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 7518Z	Veh. Inspected	SMR 8227L
Policy No.	-	Coverage	0
Claim No.	AVS24/2657	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	27/08/2024

2. Vehicle Details

Make & Model	HONDA FIT 1.3GF	C.C	1317
Engine No.	L13B3932845	Year of Reg.	23/01/2020
Chassis No.	GK33418355	Colour	GREY
Odometer	56155 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/70R14	BRIDGESTONE	6
L/H Front Tyre	175/70R14	BRIDGESTONE	6
R/H Rear Tyre	175/70R14	BRIDGESTONE	6
L/H Rear Tyre	175/70R14	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/08/2024	Inspection Date	28/08/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days