

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

Lim Tien Siong

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)  
CTPL

CLS

Singapore

LKK-

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/08/2024
Vehicle Reg. No.:	SHA3095G	Driveable?	NO
Party At Fault:	UNKNOWN		

Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	16/01/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU401755	Chassis No:	KMHC851CVLU187875
Odometer:	0 KM		

Paint Type:  
List Item Discount: 20.00 %  
Total Loss? NO  
Est. Duration of Repair (day) 4

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

**COST OF CLAIMS** **Amount**

Parts	4,379.60
Miscellaneous Items	12.00
Labour	1,830.00
Paintwork Labour	0.00
Towing	0.00
	<b>Gross Total (S\$) 6,221.60</b>
	<b>+ GST 9.00% (S\$) 559.94</b>
	<b>Nett Amount (S\$) 6,781.54</b>

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

28/8 @ 14:45hrs.

# PAIR DETAILS

## Reference

Lim Tien Siong

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Aug 2024)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA3095G/28/08/2024 14:45

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID - HYBRID / NPC	20.00	0.00	*24.30 FL
2	1		*BOOTLID - IONIQ / NPC	20.00	0.00	*31.30 FL
3	1		*BOOTLID - H / NPC	20.00	0.00	*28.00 FL
4	1		*BOOTLID / 00	20.00	0.00	*2,549.70 FL
5	1		*REAR BUMPER / BR	20.00	0.00	*459.40 FL
6	1		*REAR BUMPER REINFORCEMENT ?	20.00	0.00	*394.80 FL
7	2		*REAR BUMPER REINFORCEMENT BRKT RH / LH ?	20.00	0.00	*276.20 FL
8	1		*REAR BUMPER CENTRE MOULDING / BR	20.00	0.00	*451.25 FL
9	10		*REAR BUMPER CLIPS / NPC	20.00	0.00	*22.00 FL
10	1		*REAR BUMPER REFLECTOR LH X	20.00	0.00	*41.45 FL
11	1		*REAR BUMPER SIDE BRKT LH X	20.00	0.00	*55.80 FL
12	1		*BOOTLID - COMFORTDELGRO / NPC	0.00	0.00	*30.00 F
13	1		*BOOTLID - 65521111 / NPC	0.00	0.00	*30.00 F
14	1		*BOOTLID - ZIG / NPC	0.00	0.00	*40.00 F
15	1		*REVERSE SENSORS / BR	0.00	0.00	*180.00 F
16	1		*BOOTLID ADV.STICKER / NPC	0.00	0.00	*100.00 F
17	2		*REAR FENDER ADV.STICKER RH / LH / NPC	0.00	0.00	*200.00 F
18	2		*REAR WINDSCREEN SEALANT / NPC	0.00	0.00	*92.00 F
19	1		*REAR BUMPER TOW COVER / CUT	20.00	0.00	*98.80 FL
20	1		*REAR BUMPER FOGLAMP X	20.00	0.00	*201.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,306.50
- List Item Discount on L Items (\$\$)	926.90
<b>Total Parts (\$\$)</b>	<b>4,379.60</b>

ComfortDelGro Engineering Pte Ltd/SHA3095G/28/08/2024 14:45. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

Qty	Particulars	Unit	Price	Amount
<b>Miscellaneous Items</b>				
1	OD/TP Case (Insurer)			12.00
<b>Sub Total (S\$)</b>				<b>12.00</b>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	760 800.00
2	SPRAY PAINTING	New	560 600.00
3	TUFF KOTE	New	20 60.00
4	R/I REAR WINDSCREEN GLASSES	New	150 250.00
5	R/I REVERSE SENSORS	New	20 120.00
<b>Gross Labour Cost (S\$)</b>			<b>1,830.00</b>

ComfortDelGro Engineering Pte Ltd/SHA3095G/28/08/2024 14:45. Not valid without Reference section.  
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)  
29/8/24, 3.0pm  
m d  
L/S  
by AL by  
3 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

A: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 5952027

JC NO305602199

CUSTOMER  COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO: SHA3095G	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: IONIQ(G3)	DATE/TIME IN 28.08.2024 12:10
	YR OF MANU: 16.01.2020	TARGET DATE
	CHASSIS CODE: KMHC851CVLU187875	COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Ident Date: 27.08.2024  
RE: 3P 27.08.2024

10 LABOR CODE  
PB

DESCRIPTION  
LUMPSUM REPAIR-SHA3095G-TP



CKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHA3095G LIMTS

Vehicle No.: SHA3095G

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard