## **ESTIMATED ACCIDENT REPAIR COST**



**SBS3326S** 

ACCIDENT TIME REPORTED 07:47 HRS

ACCIDENT DATE 12-Jun-24

BUS CAPTAIN NAME LIM SOCK YEAN

THIRD PARTY SMRT

**CLAIM AGAINST** 

BUS TYPE (SD/DD)	DD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	N

**BUS REGISTRATION** 

NUMBER

## **SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)**

NO.	Part or Item Description	Quantity Total Cost		Total Cost
1	NSF VIEW MIRROR ASSY	1	\$	2,025.96
2	THIRD MIRROR VOLVO	1	\$	141.90
3	MIRROR ARM(THIRD MIRROR)	1	\$	284.26
4	REFLECTOR STICKER	2	\$	88.00
		9% GST	\$	228.61
		PARTS TOTAL COST	\$	2,768.73

## SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)			TOTAL COST	
TO DISMANTLE & REPLACE :-				
DISMANTLE AND REPLACE ITEM NO: 1-4			2,600.00	
SPRAY PAINTING \$640 PER PANEL	9% GST	\$	234.00	
LABOUR CHARGES \$650 PER DAY	LABOUR TOTAL COST	\$	2,834.00	

## SECTION 3: NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

			DATE IN	12/Jun/2024	
		DA	TE & TIME SURVEY		
			DATE OUT		
BUS TYPE (SD / DD)	DD	T	OTAL NUMBER OF DAYS	2	
	LOSS OF USE COS		\$800.0	0	

SUMMARY			
SECTION NO.		COST	
1	\$	2,768.73	
2	\$	2,834.00	
3	\$	800.00	
TOTAL	\$	6,402.73	

PAGE 1