

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC 24080500/Uvh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 636 6548C

at Workshop m/s Lee m/s

of _____

Insured: 63D 202P

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 30k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 617W

Vehicle: IN / OUT

L7A613163

Veh No: 636 6548C Yr Regn: 26/09/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (in)

Make: Nissan Cabstar C.C. 2953

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 175749 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN15C2F24X0860022

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-1215

R: 165-1213 Dunlop

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or heide

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. 28/08/24 D.O.I. 29/8/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

02/10/13

9/9/24 4/5 \$ 7500 informed MR Lee

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	017W
Vehicle Details	
Vehicle No.:	GBG6548L
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2024
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Gold
Manufacturing Year:	2016
Engine No.:	ZD30023844N
Chassis No.:	JN1SC2F24Z0860022
Maximum Power Output:	-
Open Market Value:	\$26,468.00
Original Registration Date:	26 Sep 2017
First Registration Date:	26 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,324.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,809.00
COE Rebate Amount:	\$13,163.00
Total Rebate Amount:	\$13,163.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 29 Aug 2024

OK

not Authorized
in
moral
29/8/24
d/s # 7500/
Ch. M. A. P. -
8 days

Tel : 6509 5521 / 65095524 Fax : 6509 5523

ESTIMATE

ACC DATE : 28.08.2024

GBD202P

PARTICULAR		UNIT PRICE	AMOUNT
QTY	NETT ITEM	SS	SS
1	1 FRONT BUMPER ASSY	1209.20 1,602.41	Dis 1,602.41 ✓
2	1 FRONT CAB PANEL	1408.20	DD 1408.20 ✓
3	1 FRONT CAB PANEL EMBLEM 'CABSTAR'	89.95	122 89.95 ✓
4	1 FRONT CORNER PANEL -RH	86.50	11 86.50 X
5	1 FRONT CHASSIS CROSS MEMBER -CTR	371.25	11 371.25 X
6	1 FRONT GRILLE ASSY	481.20	11 481.20 ✓
7	2 FRONT HEADLAMPS -R/L	566.01	N/SN10/S10 1,132.02 1PC
8	2 FRONT HEADLAMP LOWER GARNISHES	410.50	N/SN10/S10 821.00 1PC
9	1 FRONT WIPER PANEL	411.02	R 411.02 X
10	1 FRONT WINDSCREEN GLASS	18.60	11 18.60 X
11	1 (SET) FRONT WINDSCREEN MOULDING	195.60	11 195.60 X
12	2 REAR DOOR PILLARS -R/L	581.60	R 1,163.20 X
13	1 TAILGATE	1645.00	Body, 1645.00 ✓
14	1 TAILGATE LOWER MEMBER	372.45	DD/Snt 372.45 ✓
15	3 TAILGATE HINGES LOCK PIN	281.65	11 844.95 X
16	2 TAILLAMPS -R/L	89.95	11 179.90 ✓
17	2 TAILLAMPS BRACKETS -R/L	89.55	11 179.10 X
18	1 SIDE GATE -LH	91.50	R 91.50 X
19	1 SIDE GATE LOCK HINGE -LH	781.60	R 781.60 X
20	1 REAR SPARE WHEEL CARRIER	261.33	Daye 261.33 ✓
21	1 REAR LICENCE LAMP bracket	191.20	3ant 191.20 ✓

LESS 10%

LEE BROTHERS AUTOMOTIVE PTE.LTD

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>SPECIAL NETT ITEMS</u>			
1	1 (SET) FRONT BUMPER CLIP		nel 50.00 30
2	1 (SET) FRONT NO PLATE WITH HOLDER		Buf 60.00 30
3	1 (SET) FRONT WINDSCREEN SEALANT		nel 80.00 40
4	1 (SET) REAR REVERSE SENSOR		cre 280.00 200
5	1 (SET) REAR NO PLATE WITH HOLDER		Buf 60.00 30
6	1 REAR STICKER '70KM/H'		nel 10.00 /
7	1 REAR STICKER '6 PAX'		nel 10.00 /
			550.00

<u>LABOUR CHARGES :</u>			
1	TO CHECK FRONT AND REAR ELECTRICAL WIRING		100.00 30
2	TO REMOVE AND REPLACE FRONT WINDSCREEN		180.00 100
3	TO REMOVE AND REFIX DASHBOARD		350.00 200
4	TO REMOVE AND REPLACE REVERSE SENSOR		60.00 30
5	TO TUFF KOTE		150.00 80
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		2,000.00 / 200
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		2,200.00 / 580
TOTAL:			5,040.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 14,624.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

26488.44
102
5840.50
350
3220
9410.50
206
7528