



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS INCOME INSURANCE LTD		Ref:		CS/INC24080500/Uvh3
75 BRAS BASAH ROAD		Date:		12/09/2024
INCOME CENTRE SINGAPORE 189557		Code:		INC
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 202P		Veh. Inspected	GBG 6548L
Policy No.	-		Coverage	0
Claim No.	MT/1292868-001		Excess	\$0.00
Assign From	AMANDA CHOOI		Assign Date	29/08/2024
2. Vehicle Details				
Make & Model	NISSAN CABSTAR (M)		C.C	2953
Engine No.	ZD30023844N		Year of Reg.	26/09/2017
Chassis No.	JN1SC2F24Z0860022		Colour	GOLD
Odometer	175749 KM		Steering	IN ORDER
Brakes	IN ORDER		General	GOOD
Modification(s)	RIMS: NIL RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	195R15	HAIDA	6	
L/H Front Tyre	195R15	HAIDA	6	
R/H Rear Tyre	165R13 (D)	DUNLOP	6/6	
L/H Rear Tyre	165R13 (D)	DUNLOP	6/6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/08/2024		Inspection Date	29/08/2024 (12:04)
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				