REF: CS3/SPF24080503/Avp3

ASSIGNMENT

From: Date:

Estin. Cost:

OD / TP RES / OD RES / EVA / INV / MV

To in Vehicle No:

at W/s m/s

of

Insured: TP 357A

Policy No

Claims No. ACS/105/009/2024/043(LK)

Sum Ins: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMM348A Yr Regn: 2019, June,

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Freed c.c 1496

Colour Blue. A/C: Insured / Std / NI / NA

Sp.Reading 185514. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GB71075803.

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / (STD A/Rim) or

Tyre Size: F: 185/65R15

R: 185/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Fortune

Front		Rear	
R/Bal. 06 mm		R/Bal. 06 mm	
L/Bal. 06 mm		L/Bal. 06 mm	

D.O.A. 22/8/2024 D.O.I. 27/08/24

Survey held at Infinity Auto 57

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP SPF. PRS. COE Expiry: ✓
24/1/25	submit DAR LS $5850
	Estimate given during 1st Survey ✓ : Yes ( ) No (✓)
	MV:
	PV:
	Nett:
	757C

Date/Time, File Pass to? [ ] : Preli. Report

1) [ ] : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($) [ ] : Interview ($) [ ] : Tech. Inve ($)

Survey Fee:

Transportation: $ + R.S. $

Photos

Others

Report Format: