

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CS/SMR24090011/4vp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: G3D9539J

at Workshop m/s hockner 2nd

of _____

Insured: SHB 218J SHB50862

Policy No. _____

Claims No. TAX/08/24/2095

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: 610k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 3 5-94/c

Vehicle: IN / OUT

Date: _____ Person Contacted: 2149454

Veh No: G3D9539J Yr Regn: 02/08/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or .CM /

Make: Nissan cabstar c.c 2953

Colour: S.hu A/C: Insured / Std / NI / NA

Sp.Reading: 291665 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1SC2F242*0857440

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15 35

R: 165 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front 6 mm Rear 6/6 mm

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm


D.O.A. 28/08/24 D.O.I. 10/9/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction 18/9/24 1/5 @ 1200 : Inform Jeyi (red 3510.43, 74%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$) S + RS, SI

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$) TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____)

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	594K
Vehicle Details	
Vehicle No.:	GBD9539J
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Sep 2024
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	ZD30001174N
Chassis No.:	JN15C2F24Z0857440
Maximum Power Output:	-
Open Market Value:	\$25,089.00
Original Registration Date:	03 Aug 2015
First Registration Date:	03 Aug 2015
Transfer Count:	1
Actual ARF Paid:	\$1,255.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,062.00
COE Rebate Amount:	\$454.00
Total Rebate Amount:	\$454.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 09 Sep 2024

OK

Home>Used Cars>Listing

All Category

Search

Save Search

- 2015
- 9 Vehicles
- Car Make

Car Model

Price Range

Depreciation

2015

Mileage
- 

Nissan Cabstar 3.0M

\$10,800

Instl. \$910 /mth

\$10,240 /yr

01-Oct-2015

N.A

1 Owner

Diesel

One owner only! Engine and gearbox in good condition. No repair needed. Call for viewing.

Posted 09-Sep-2024

Compare
- 

Nissan Cabstar 3.0M

\$11,500

Instl. \$969 /mth

\$11,340 /yr

16-Sep-2015

N.A

1 Owner

Diesel

Selling cheap. 1 years balance. Good for coe renewal.

Posted 04-Sep-2024

Compare
- 

Nissan Cabstar 3.0M

\$12,800

Instl. \$1,183 /mth

\$12,910 /yr

08-Sep-2015

150,300 km

2 Owners

Diesel

Well maintained truck. New interior and exterior paintwork, good working condition, free 3 times servicing by our in house workshop. High in house loan available, high trade in value and welcome dealer. Contact our sales advisor now to book an appointment!

Posted 03-Sep-2024

Compare

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53226594K
XUE FANG TRADING SERVICES
NO

SINGAPORE
TEL : FAX :
PH : 97371619
ATTN :

ESTIMATE BILL

Number : EB00006565
Date : 30/08/2024
Case No : AD00014923
Vehicle No : GBD9539J
Chassis: JN1SC2F24Z0857440
Year of Mfr 2015
Policy No MZD00095
Model : NISSAN CABSTAR 3.0
5M/ABS 2DR 2WD

Term:

Sn	DESCRIPTION	QTY	U PRICE	EURO5 DISC	AMOUNT
1	TAILGATE	1.0	1,624.50	30	1,137.15
2	TAILGATE STICKER - NISSAN	1.0	47.00	30	32.90
3	TAILGATE STICKER - 70KM/H	1.0	20.00	30	14.00
4	TAILGATE SIDE LOCK LH	1.0	35.00	30	24.50
5	TAILGATE SIDE LOCK RH	1.0	35.00	30	24.50
6	TAILGATE TOP LOCK LH	1.0	120.00	30	84.00
7	TAILGATE TOP LOCK RH	1.0	120.00	30	84.00
8	REAR REVERSE SENSOR LH	1.0	350.00	30	245.00
9	REAR REVERSE SENSOR RH	1.0	350.00	30	245.00
10	TAIL LAMP LH	1.0	206.70	30	144.69
11	TAIL LAMP RH	1.0	206.70	30	144.69
12	TAIL LAMP PANEL LH	1.0	160.00	30	112.00
13	TAIL LAMP PANEL RH	1.0	160.00	30	112.00
14	REAR STEP BAR	1.0	360.00	30	252.00
15	REAR END PANEL	1.0	380.00	30	266.00
16	TAIL GATE ALUMINIUM PANEL	1.0	350.00	30	245.00
17	REAR STOPPER LH	2.0	10.00	30	14.00
18	REAR STOPPER RH	2.0	10.00	30	14.00
List Price - Parts Sub Total					3,195.43
19	TAILGATE HINGE	3.0		30	
20	TAILGATE PIN	3.0		30	
21	TAILGATE LOCK RING	3.0		30	
22	REAR FLOOR PANEL - REPAIR	1.0			
23	REAR CARGO BOX - REPAIR	1.0			
24	REAR NUMBER PLATE	1.0	35.00	0	35.00
Special Nett Price - Parts Sub Total					35.00
Parts Total					3,230.43
25	TWO WHEEL ALIGNMENT	1.0	100.00	0	100.00
26	ANTI-RUST COATING	1.0	100.00	0	100.00
27	TO REMOVE & REFIT REVERSE SENSOR	1.0	180.00	0	180.00
28	WIRING	1.0	100.00	0	100.00
29	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
30	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts for resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis

CUSTOMER SIGNATURE modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Page 1 of 2

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Acknowledged by Repairer
Signature:
Date:

Issued by : Michelle

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53226594K
XUE FANG TRADING SERVICES
NO

SINGAPORE
TEL : FAX :
PH : 97371619
ATTN :

ESTIMATE BILL

Number : EB00006565
Date : 30/08/2024
Case No : AD00014923
Vehicle No : GBD9539J
Chassis: JN1SC2F24Z0857440
Year of Mfr 2015
Policy No MZD00095
Model : NISSAN CABSTAR 3.0
5M/ABS 2DR 2WD

Term:

Sn	DESCRIPTION	QTY	U_PRICE	EURO 5 DISC	AMOUNT
	Labour 1 Sub Total				1,480.00
SINGAPORE DOLLARS : FIVE THOUSAND ONE HUNDRED THIRTY-FOUR AND CENTS THIRTY-SEVEN ONLY			Less Excess		0.00
			SUBTOTAL		4,710.43
			GST 9.00%		423.94
			TOTAL		5,134.37

Date of accident : 28/08/2024 06:15 PM. Place : SLIP ROAD OF UPPER CHANGI ROAD TOWARDS PIE TUAS

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST