

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automobile	
MS	INCOME INSURAN	ICE LTD	Ref:	CS/INC24060138/Aqh3	
	75 BRAS BASAH F		Date:	10/09/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 5130P	Veh. Inspected	SLZ 6475U	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1282304-001	Excess	\$0.00	
	Assign From	SHAFAWATI BINTE MD RABU	Assign Date	19/06/2024	
2. Vehicle Details					
	Make & Model	HONDA VEZEL HYBRID	C.C	1496	
	Engine No.	LEB5961042	Year of Reg.	14/05/2018	
	Chassis No.	RU31261025	Colour	WHITE	
	Odometer	163735 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.		Conditions of Tyres			
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60 R16	MATRAX	6	
	L/H Front Tyre	215/60 R16	MATRAX	6	
	R/H Rear Tyre	215/60 R16	MATRAX	6	
	L/H Rear Tyre	215/60 R16	MATRAX	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
DAN	MAGES SEE DETAIL	.S.			
5.	. General Information				
	Accident Date	18/06/2024	Inspection Date	19/06/2024 (16:10)	
	Survey held at JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
B) IN	NACCORDANCE I	D TOOK INSTRUCTIONS, WE TAVE I	101 AOTHORIOLD I	ALI AINO.	

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days