



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS GREAT AMERICAN INSURANCE COMPANY		Ref: CS/GAI24090035/Tvp3e2		
3 TEMASEK AVENUE		Date: 03/09/2024		
#16-01 CENTENNIAL TOWER		Code: GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 9014M	Veh. Inspected	SMB 1559J	
Policy No.	-	Coverage	0	
Claim No.	CLMOMVP000001584	Excess	\$0.00	
Assign From	JEANNIE ANG	Assign Date	02/09/2024	
2. Vehicle Details				
Make & Model	MAN NL 320F (A22)	C.C	10518	
Engine No.	50339002253910	Year of Reg.	23/12/2014	
Chassis No.	WMAA22ZZ3F7002517	Colour	MULTI COLOUR	
Odometer	713253 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: NIL			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	275/70 R22.5	GOODYEAR	8	
L/H Front Tyre	275/70 R22.5	GOODYEAR	8	
R/H Rear Tyre	275/70 R22.5 (D)	GOODYEAR	8/8	
L/H Rear Tyre	275/70 R22.5 (D)	GOODYEAR	8/8	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/08/2024	Inspection Date	03/09/2024	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				