

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/08/2024

User ID : choonhwee03

Section A - Accident Details	
Registration Number	SMB1559J
Case Reference Number	BUS/08/24/5057
Registration Date	12/23/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Charlie Kam Chong Nyen
Type of Accident	Head To Side
Accident Date and Time	8/28/2024 5:50 AM
Accident Reported Date and Time	8/28/2024 9:51 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB1559J - FRONT LEFT PORTION SLW9014M (TP) - INSURED WITH Great American Insurance Company
Prepared Date and Time	8/30/2024 9:42 AM
Chassis Number	WMAA22ZZ3F7002517
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$2,708.18	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,006.18	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2 DAYS
Prepared / Adjusted By	Jeong Choon Hwee	Taufikh
ARC / Surveyor Sign Off Date	30/08/2024 10:15 AM	3/9/24
Signature		
Remarks		Taufikh 97495749 WP 3/9/24 L/S RESURVEY AFTER REPAIR taufikh@LKKauto.com

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/08/2024

User ID : choonhwee03

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				1060		
Total Labour			\$1,590.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$708.00				616		
Total Spray Painting & Panel Beating			\$708.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW264	COVER,HEADLAMP:FRT ,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	CRA ✓
6010307	VE	81.25320-6112	FLASHER,AUX HEADLAMP,RH (MAN BUS)	1.00	\$904.40	0.00	\$904.40	Replace	CRA ✓
6010304	VE	8-25101-6539	HEADLAMP,LH (MAN BUS)	1.00	\$1,603.60	0.00	\$1,603.60	Replace	CRA ✓
6010073	Body	F01001-CW262	DOME:FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	XR
6009375	VM		RETAINER:MALE & FEMALE,REAR LID,MAN BUS	1.00	\$74.80	10.00	\$67.32	Replace	DIS ✓
Total					\$6,375.00		\$3,452.55		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									