LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

INV No.: SAC2400590

INV Date: 11-09-2024

Reference CS/SMR24090040/Uvp3

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SNP 2370T Insured Veh. SHB 1183T

Claim No. TAX/08/24/2105

Policy No.

Accident Date 31/08/2024 Inspection Date 03/09/2024

Description	Amount
Survey Inspection	128.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En	Automobile
MS	STRIDES PREMIE	R AUTOMOTIVE SERVICES PL.	Ref:	CS/SMR24090040/Uvp3
	60 WOODLANDS I 757705	NDUSTRIAL PARK E4 SINGAPORE	Date:	11/09/2024
			Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM				IM
	Insured Veh.	SHB 1183T	Veh. Inspected	SNP 2370T
	Policy No.	-	Coverage	0
	Claim No.	TAX/08/24/2105	Excess	\$0.00
	Assign From	HUA YEN	Assign Date	03/09/2024
2.		Vehicle	Details	
	Make & Model	HONDA SHUTTLE (A)	C.C	1496
	Engine No.	L15B5462536	Year of Reg.	25/06/2018
	Chassis No.	GK81202179	Colour	RED
	Odometer	145752 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.		Condition	s of Tyres	
		Size	Make	Balance (mm)
	R/H Front Tyre	195/50R16	HANKOOK	6
	L/H Front Tyre	195/50R16	HANKOOK	6
	R/H Rear Tyre	195/50R16	HANKOOK	6
	L/H Rear Tyre	195/50R16	HANKOOK	6
4.		Description	of Damages	
THE	VEHICLE SUSTAIN	NED DAMAGES AT THE REAR PORTION	ON.	
DAN	MAGES SEE DETAIL	.S.		
5.		General II	nformation	
	Accident Date 31/08/2024 Inspection Date 03/09/2024		03/09/2024	
	Survey held at	FASTECH AUTO PTE LTD - 1 KAKI E 417883	BUKIT AVENUE 6 #0	1-46/48/50 AUTOBAY SINGAPORE
5a.		Ren	narks	
		AS CONDUCTED ON A"WITHOUT PR O YOUR INSTRUCTIONS, WE HAVE N		REPAIRS.
5b.		Estimate Da	ys of Repair	

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNP 2370T

	REPLACEMENT OF PARTS			
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN MOULDING	NECESSARY	\$166.20	\$166.20
1	TAILGATE	BADLY DENTED	\$1,455.20	\$1,193.00
1	TAILGATE REAR LOGO	CRACKED	\$48.00	\$48.00
2	TAILGATE REFLECTORS @\$341.60	SERVICEABLE	\$683.20	\$0.00
1	TAILGATE OUTER GARNISH	CRACKED	\$495.00	\$381.20
1	TAILGATE INNER LOCK	BENT	\$288.20	\$245.50
1	TAILGATE INNER TRIM BOARD	DEFORMED/TORN	\$455.10	\$455.10
1	TAILGATE WEATHERSTRIP	TWISTED	\$232.80	\$232.80
2	TAILLAMPS @\$950.00	CRACKED	\$1,900.00	\$1,160.00
1	REAR BUMPER	DENTED/DEFORMED	\$1,415.10	\$985.00
2	REAR BUMPER SIDE RETAINERS @\$45.00	NOT NECESSARY	\$90.00	\$0.00
2	REAR BUMPER REFLECTORS @\$75.00	NOT NECESSARY	\$150.00	\$0.00
2	REAR BUMPER SIDE COVERS @\$111.00	N/S NOT NECESSARY / O/S TWISTED	\$222.00	\$111.00
2	REAR BUMPER INNER SPONGES @\$150.00	N/S NOT NECESSARY / O/S TORN	\$300.00	\$148.00
1	REAR END PANEL	DENTED/BENT	\$755.20	\$615.00
1	REAR END PANEL TOP GARNISH	TWISTED	\$248.70	\$248.70
1	REAR END PANEL ANTENNA SENSOR	NOT NECESSARY	\$108.90	\$0.00
2	REAR END PANEL SIDE EXTENSION PANELS @\$285.00	TO REPAIR SEE LABOUR	\$570.00	\$0.00
1	REAR EXHAUST	NOT NECESSARY	\$688.20	\$0.00
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	\$544.10	\$0.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	\$1,140.20	\$0.00
1	REAR FLOOR PANEL TOOLS TRAY	TWISTED/CRACKED	\$652.30	\$481.20
2	REAR FENDER INNER TRIM BOARDS @\$690.00	DEFORMED/TORN	\$1,380.00	\$910.00
1	REAR FENDER	TO REPAIR SEE LABOUR	\$1,155.20	\$0.00
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$1,476.14)
			\$15,143.60	\$5,904.56

	Special Nett			
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$50.00	\$40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	\$50.00	\$20.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Special Nett			
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	\$280.00	\$0.00
1	SET TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	\$50.00	\$40.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$60.00	\$30.00
1	REAR BUMPER LOWER SPOILER (SN)	DENTED/DEFORMED	\$900.00	\$600.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	\$50.00	\$50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	\$200.00	\$0.00
	·		\$1,640.00	\$780.00

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$
TO CHECK WIRING		\$50.00	\$20.00
TO DISMANTLE & REFIX REVERSE SENSOR		\$80.00	\$30.00
TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	\$120.00
TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	\$60.00
TO TRANSFER TAILGATE MECHANISM		\$100.00	\$60.00
TO SPRAY RUST PROOFING		\$100.00	\$50.00
TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM	NOT NECESSARY	\$120.00	\$0.00
LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL SIDE EXTENSION PANELS, REAR FLOOR PANEL AND REAR FENDER		\$1,800.00	\$600.00
TO PUTTY & SPRAY PAINTING		\$1,800.00	\$800.00
•		\$4,320.00	\$1,740.00
GRAND TOTAL \$21,103.60			\$8,424.56

GRAND TOTAL	\$21,103.60	\$8,424.56	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$6,700.00	
Report Ref No: CS/SMR24090040/Uvp3			

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 02/09/2024 17:24 (SGT) Reported by **Actual Driver** Date of Accident 31/08/2024 10:00 (SGT) Exact Location of Accident Singapore Additional Location Information SIMS AVENUE Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNP2370T

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner ONG WEE HUAT NRIC No S8721628D Email Address MICHAEL.ONG87@GMAIL.COM Mobile Phone No (Phone) +65-97838242 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Honda Model Shuttle Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC Vehicle Fuel Petrol First Regisration Date 25/06/2018 Chassis no GK81202179 Effective Date/Time of Ownership 25/06/2018 00:00 (SGT)

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited Policy Number / Cover Note Number 5142919716

DRIVER

Name of Driver NG KOK HENG NRIC No S1503187E Date Of Birth 29/10/1961 Occupation Outdoor Driving Pass Date 18/02/1983 Driving License Pass Class Driving License Validity Valid Driving experience 41 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-98569975 Alt. Phone Number Email Address KOKHENGKHNG@GMAIL.COM Address APT BLK 106 ALJUNIED CRESCENT #02-205 Address complement Postcode 380106 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Relative Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement **DETAILS OF POLICE ACTION** Was the accident reported to the police? Yes Police Station Name Traffic Police Police Station Phone No (Phone) +65-65470000 Alt. Police Station Phone No (Fax) +65-65474900 Police Station Address 10 Ubi Avenue 3 Singapore 408865 Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED ATTACHMENT(S) Are accident photos available for attachment? Yes

No

Was there any video captured by Car Camera?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB1183T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Gender Phone No Address Address Complement	NG KOK HENG Male (Phone) +65-98569975 APT BLK 106 ALIUNIED CRESCENT #02-205
Post Code	380106
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SNP2370T
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>Intitutal and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the ladgement of this report to the incurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

f understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") maylare permitted to collect, use, disclose ancifor process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lewyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) Investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invaices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopesimal packages); and/or

(v) complying with applicable law in administering, processing, handling end/or dealing with my claims.(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Ø 2 Sep 2024


Policyholder's Signature / Date & Time

Actual Driver's Signature (# driver is not the policyholder) / Date & Time

LENG

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



WHITE U.S.

⊉ Please	construction accident	11201-40 10-4 100	<u></u>
-			
	7.000		
	2-1		
	11810		
Declaration I/We declare the fo	regoing particulars are true in every respect.		
ند			
Ø,	2 Sep 2024		LENG





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 3 Report No. T/20240902/7059

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/09/2024 13:46		Vide Report No.:	Station Diary No	
Informan	t's Particular	S		
Name of Informant: Address: NG KOK HENG 106 ALJUNIED CRESCENT #02-205 SINGAPORE :		NT #02-205 SINGAPORE 380106		
ID Type / ID No.: NRIC NO / S1503187E		Contact No.: Home/Office:		
Nationali SINGAP	ty: ORE CITIZE	N	Email: kokhengkhng@gmail.com	
Sex: Male	Age: 62	Date of Birth: 29/10/1961	Type of Informant: Driver	
Race: Chinese			Language: English	
Occupation: plumbing engineering		Driving Licence Informatio Class: 28,3	n: Date of Expiry:	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/08/2024 10:00	Type of Location X-Junction
Location:				
SIMS AVENUE				
Weather:		Road Surface:		
		Road Surface: Dry		
Clear Traffic Flow:		Dry Traffic Control:		ffic Volume:
Weather: Clear Traffic Flow: One Way		Dry		

Type	Make	Model	Color	Condition	No of Passenge
Motor car					1
Motor car	HONDA	shuttle	Red	Seriously	0
	Motor car				

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective Date	Expiry Date
SNP2370T	NTUC Income Insurance Co-Operative Limited	5142919716	29/01/2024	28/01/2025



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T/20240902/7059

CONTINUATION OF REPORT

Details of Person	Involved				NE E III BUYY
Any Pedestrian In	volved: No				
No. of Pedestrians	Use of Pedestrian Crossing, NA				
Driver					
Name	NG KOK HENG		ID No		S1503187E
Related Vehicle	SNP2370T (Motor car)		Conta	ct No.	98569975
Hospital/Clinic	NIL		Class Drivin Licent Expiry	g >e &	Class: 28,3 Date of Expiry: NIL
Date Treatment	02/09/2024	Date Disch	arge	02/09	/2024
No. of Days granted Medical Leave (MC) 05		Degree of I	agree of Injury Sen		us

Brief Details.

31.08.2024 at about 10:00am. I was travelling along SIMS AVENUE. Due to the traffic light being red, I stopped in place, Suddenly, I felt an impact. Vehicle B (SHB 1183T) collided with the rear of my vehicle (SNP 2370T). During the accident no passenger was in my vehicle.

As a result of the accident, I felt pain on my neck, shoulder and back. I visited to NORWOOD MEDICAL HOUGANG after the accident. The doctor gave me 5 days MC.

⁻ My vehicle no video.



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



3 of 3 Report No. T/20240902/7059

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 02/09/2024 13:46
Officer In Charge Of Case: TP / AEIT / CHUA SOON KEONG Contact No.: 65476030	Classification Of Case:
NP168	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 1 of 16)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 2 of 16)













INSPECTION PHOTOS (Page 3 of 16)













INSPECTION PHOTOS (Page 4 of 16)













INSPECTION PHOTOS (Page 5 of 16)















INSPECTION PHOTOS (Page 6 of 16)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 7 of 16)













INSPECTION PHOTOS (Page 8 of 16)













INSPECTION PHOTOS (Page 9 of 16)













INSPECTION PHOTOS (Page 10 of 16)














INSPECTION PHOTOS (Page 11 of 16)













INSPECTION PHOTOS (Page 12 of 16)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 13 of 16)













INSPECTION PHOTOS (Page 14 of 16)













INSPECTION PHOTOS (Page 15 of 16)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 16 of 16)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 1 of 21)













REINSPECTION PHOTOS (Page 2 of 21)













REINSPECTION PHOTOS (Page 3 of 21)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 4 of 21)













REINSPECTION PHOTOS (Page 5 of 21)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 6 of 21)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO.: SNP 2370T









REINSPECTION PHOTOS (Page 7 of 21)





REINSPECTION PHOTOS (Page 8 of 21)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 9 of 21)













REINSPECTION PHOTOS (Page 10 of 21)













PHOTOGRAPHS FOR VEHICLE NO.: SNP 2370T









REINSPECTION PHOTOS (Page 11 of 21)





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 12 of 21)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 13 of 21)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 14 of 21)













REINSPECTION PHOTOS (Page 15 of 21)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO.: SNP 2370T









REINSPECTION PHOTOS (Page 16 of 21)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 17 of 21)













REINSPECTION PHOTOS (Page 18 of 21)













REINSPECTION PHOTOS (Page 19 of 21)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 20 of 21)














REINSPECTION PHOTOS (Page 21 of 21)







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REINSPECTION PHOTOS (Page 1 of 3)











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO.: SNP 2370T









REINSPECTION PHOTOS (Page 2 of 3)





REINSPECTION PHOTOS (Page 3 of 3)

