



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090048/Rnp3e2
16 RAFFLES QUAY	Date:	23/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4168T	Veh. Inspected	GBE 6182T
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007577MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	03/09/2024

2. Vehicle Details

Make & Model	CITROEN BERLINGO 1.6L	C.C	1560
Engine No.	10JBFR0023364	Year of Reg.	15/02/2016
Chassis No.	VF77F9HF8FJ858923	Colour	WHITE
Odometer	146209 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	WEST LAKE	6
L/H Front Tyre	195/65 R15	WEST LAKE	6
R/H Rear Tyre	195/65 R15	WEST LAKE	6
L/H Rear Tyre	195/65 R15	WEST LAKE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/08/2024	Inspection Date	03/09/2024
Survey held at	R&S ENGINEERING WORKS PTE LTD 13, PIONEER SECTOR 1, SINGAPORE 628424		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days