



Your Ref : CLMOMVP000001584

Date: 23rd September 2024

Our Ref : CS/GAI24090075/Tnp3

M/s Great American Insurance Company

3 Temasek Avenue

#16-01 Centennial Tower

Singapore 039190

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLW 9014M
ACCIDENT ON 28/08/2024**

Instruction was received to inspect the vehicle Reg. No. SLW 9014M. The inspection was conducted on 04/09/2024 at Carros Centre 60 Jalan Lam Huat #05-01, Singapore 737869
Repairer: M/s Vin's Motor Pte Ltd.

The following vehicle information was recorded:

Registration Number	: SLW 9014M
Make/Model	: Opel Mokka X 1.6 Cdti 6at (Led)
Year of Registration	: 2018
Body Colour	: Bronze
Chassis Number	: W0LJD7EC8HB126965
Engine Capacity	: 1598 cc
Speedometer Reading	: N/A

The vehicle sustained damages at the front o/s, rear o/s, rear portion, undercarriage and rooftop. The body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 48,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 29,251.00)
Nett Liability	<u>S\$ 18,749.00</u> =====

Vehicle Inspected By:



MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.