

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24090080/Anh3m4	
	75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Date:	22/11/2024	
	NCOME CENTRE SINGAPORE 18955/		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJR 4630S	Veh. Inspected	SLK 7913U	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1293501-002	Excess	\$0.00	
	Assign From	JEFF LIN	Assign Date	04/09/2024	
2.	2. Vehicle Details				
	Make & Model	MAZDA 3	C.C	1496	
	Engine No.	P520383976	Year of Reg.	26/01/2017	
	Chassis No.	JM6BN22A8H0100741	Colour	RED	
	Odometer	131417 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/40R18	NEXEN	6	
	L/H Front Tyre	225/40R18	NEXEN	6	
	R/H Rear Tyre	225/40R18	NEXEN	6	
	L/H Rear Tyre	225/40R18	NEXEN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5. General Information					
	Accident Date	03/09/2024	Inspection Date	05/09/2024 (15:05)	
	Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PR	EMIER @ KAKI BU	KIT, SINGAPORE 415875	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days