

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI24090091/Rqp3e2	
	16 RAFFLES QUAY		Date:	04/11/2024	
	#42-01 HONG LEONG BUILDING SINGAPORE 048581		Code:	FCI2	
_			-		
1.	Insured Veh. SHA 1121C Veh. Inspected SGX 6556P				
		SHA 1121C	Veh. Inspected		
	Policy No. Claim No.	- D24007769MFCT	Coverage Excess	\$0.00	
		JIMMY		05/09/2024	
_	Assign From		Assign Date	05/09/2024	
Vehicle Details Make & Model VOLVO S60 T5 A/T C.C 1969					
	Make & Model	VOLVO S60 T5 A/T		1969	
	Engine No.	B4204T111900531	Year of Reg.	31/03/2017	
	Chassis No.	YV1FS40LDH2434505	Colour	BLACK	
	Odometer	65306 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/50 R17	MICHELIN	6	
	L/H Front Tyre	215/50 R17	MICHELIN	6	
	R/H Rear Tyre	215/50 R17	MICHELIN	6	
	L/H Rear Tyre	215/50 R17	MICHELIN	6	
4.	Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
	Accident Date	02/09/2024	Inspection Date	23/09/2024	
	Survey held at	held at 42 TOH GUAN ROAD EAST ENTERPRISE HUB #01-79 - REPAIRER: WAH HONG MOTORS & CREDIT PTE LTD			
5a. Remarks					

- A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
- B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
- C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days