

REF:

REF: CS/FCI 24090091/Rgp3

8284

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHX6556P

at Workshop m/s WAH HONG

of TD 4 HUAN RD 2957

Insured: FCL

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) 100m

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 54k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHX6556P Yr Regn: 2011 / NKK

Type: MC / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLVO S60 T54T cc 1969

Colour: BLACK AC: Insured / Std / NI / NA

Sp. Reading: 65306 T/Radio: Insured / Std / NI / NA

Eng/No: _____

CNo: 4U1FS40LDH2434505

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / STD / STD Airline or

Tyre Size: F: 215/50R17

R:

BS / DUN / EXMOVA / GY / PS / LIZA / MC / OHTSU / PR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 02/09/24 D.O.I. 23/09/24

Survey held at TB HUAN

Des. of Damages: Fnt / Rear / O/S / N/S / UNC / Roof/Top or

6/5 FRT

The UNC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

REPAIR LIMIT- 22K

Rasul finalised LS \$3650, 4 days (Red \$5530, 60%).

Date/Time, File Path to?

Prell. Report

11

Final Report

Order/Trans. File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Feb:

Temperature

24

Add Fee: ☐ : Site Insp (\$

11-5-75

1. Protein

) Other

Report Format : TP

Lump Sum H.B.I. (\$ 3650

Interview (3)

Tech. Invs (\$)

☐ : Weekend (\$)

TOTAL



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SGX6556P-VOLVO S60

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Headlamp RH <i>sur</i> ✓		2712.00	
1	Front bumper <i>repl</i> ✓		2278.00	
1	Front bumper side retainer RH <i>?</i>		80.00	
1	Front fender RH <i>repl</i> ✓		1350.00	
1	Side mirror RH <i>?</i>		624.00	
1	Side mirror motor RH <i>x</i>		426.00	
1	Side mirror cover RH <i>mis</i> ✓		216.00	
1	Side mirror glass RH <i>x</i>		164.00	
1	Front door RH (Repair refer to labour)		0.00	
1	Rear door RH (Repair refer to labour)		0.00	
1	Rear fender RH (Repair refer to labour)		0.00	
			7850.00	
		-10%	-785.00	
			7065.00	
	<u>SPECIAL NETT ITEMS</u>			
1	Front bumper clip <i>mis</i> <i>x</i>		35.00	
	Total Parts		7100.00	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Vehicle No. SGX6556P-VOLVO S60

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00 400	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00 400	
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00 40	
4	To perform anti-rust treatment on affected areas	90.00 40	
6	To remove, replace and focus headlamp	100.00 30	
Labour Total :		2080.00	
TOTAL (PARTS & LABOUR):		9180.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

Resue
Hp 9601w68
4 days
L/S
23/09/24
Resy after
repair

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	828H
Vehicle Details	
Vehicle No.:	SGX6556P
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2024
Vehicle Make:	VOLVO
Vehicle Model:	S60 T5 A/T ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	B4204T111900531
Chassis No.:	YV1FS40LDH2434505
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$26,641.00
Original Registration Date:	31 Mar 2017
First Registration Date:	31 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$29,298.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2027
PARF Rebate Amount:	\$17,578.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$13,601.00
Total Rebate Amount:	\$31,179.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Sep 2024

OK



Volvo S60 T5 R-Design Sunroof

\$64,800 Instalment \$1,320/mth

PREMIUM AD

💰 Apply for 2.48% loan

♡ Shortlist

✔ Get Warranty

mycarforum

TRENDING DISCUSSIONS

Component speakers, no amp?

READ MORE >

Overview Financial Photo Research

Depreciation	📘 \$14,880 / year
Reg. Date	29-Nov-2017 (3yrs 2mths 5days COE left)
Manufactured	📘 2017
Mileage	117,266 km (17.2k / year)
Transmission	Auto
Engine Cap	1,969 cc
Road Tax	📘 \$1,176 / year
Power	180.0 kW (241 bhp) View specs of the Volvo S60 (2014-2019)
Curb Weight	📘 1,612 kg
COE	📘 \$57,414
OMV	📘 \$30,675
ARF	📘 \$34,945
Dereg Value	📘 \$40,977 as of today