

REF: CS/INC24090105/Avh3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: \_\_\_\_\_

OD / TP / TP RES / CD RES / EVA / INV / MVTo in Vehicle No: \_\_\_\_\_at W/O 100 m/s

of \_\_\_\_\_

Insured: **SKR 6647U**

Policy No: \_\_\_\_\_

Claims No: **MT/1292855-002**

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Vehicle: \_\_\_\_\_

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repair: \_\_\_\_\_ days Res.: Yes or No

Turn Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SM 6 1730 D**Yr Regn: **2018 / Nov**Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Tapta Noah Hybrid****1797**Colour: **White**

A/C: Insured / Std / NI / NA

Sp. Reading: **152640**

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **ZWR800339497**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **195/65 R15**R: **195/65 R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. **06** mmR/Bal. **06** mmL/Bal. **06** mmL/Bal. **06** mmD.O.A. **28/8/2024**D.O.A. **09/09/24**Survey held at **Itua May**Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

**TP INC**

20/9/24 Adrian confirmed LS \$8700 (red 12,899.91, 59%)

COE Expiry: \_\_\_\_\_

Estimate given during: Yes ☒ No ☐1st Survey: Yes ☐ No ☒

MV: \_\_\_\_\_

PV: \_\_\_\_\_

Nett: \_\_\_\_\_

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: **6**

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐

Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Inve (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

Report Format: \_\_\_\_\_

Report Date: \_\_\_\_\_