



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS

Ref: CS/INC24090106/Aqh3e2(N)

Date: 23/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 632M	Veh. Inspected	SLH 6444D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1293704-002	Excess (\$)	0.00
Assign From	MARCUS	Assign Date	05/09/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31213729	Colour	BRONZE
Odometer	169974 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	HABILEAD	6 mm
L/H Front Tyre	215/60 R16	HABILEAD	6 mm
R/H Rear Tyre	215/60 R16	HABILEAD	6 mm
L/H Rear Tyre	215/60 R16	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2024	Inspect Date / Time	12/09/2024 (01:15 PM)
Survey held at	CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------