

(08/11/13) wef

ASS. REC. BY:

REF: CS/ICS 24090115/Rgp3

8560

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 1386C

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 1386C

Yr Regn:

2021 APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAZDA 6 2.0 EXE

c.c. 1998

Colour

GREEN

AC: Insured / Std / NI / NA

Sp. Reading

13328

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2M64L1073M0454220

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

03/09/24

D.O.I.

13/09/24

Survey held at

TANJONG P

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT 56K

07/11/24 Afq informed that they repudiate the claims as their insd breach the policy.

07/11/24 Submit Preli. report.

Date/Time, File Pass to?



Preli. Report



Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

) \$ + RS \$

) Photos

) Others

Report Format: MER-TP

Lump Sum / I.B.I. (\$

TOTAL



QUOTATION

CODE: E0139
CUSTOMER: ECICS LIMITED
ADDRESS: 7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

PAGE NO.: 1
DOCUMENT NO.: 2679
DOCUMENT DATE: 04/09/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15568
REF. NO.: DS/SLU1386C/2048
DATE IN:
EXT. WTY: 19/04/2026
MILEAGE: 0

CONTACT NO.: 6337 4779
MODEL: MAZDA6 IPM5 2L SDN EXECUTIVE B
CHASSIS NO.: JM6GL1073M0454220
ENGINE NO.: PE21596479
REG NO.: SLU1386C
REGN DATE: 20/04/2021

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	SLU1386C -TP Claim -ECICS -DOA:4/9/24				0.00	O
SUB	TO REMOVE & REPLACE FRT BUMPER.			792	1,584.00	S
	AND ALL ACCIDENT AFFECTED AREA.					
SUB	TO RESPRAY FRT BUMPER.			756	1,512.00	S
SUB	TO TRANSFER FRONT SENSORS.			180	330.00	S
SUB	TO CHECK ELECTRICAL SYSTEM			150	250.00	S
	FOR PROPER FUNCTIONING.					
SUB	TO REPROGRAMME AFTER THE			250	300.00	S
	ACCIDENT REPAIR WORKS.					
SUB	SUNDRIES.			20	50.00	S
GSJ8-50-031 BB	FRT BUMPER GL3 W/PS <i>de</i>	1.00	1,177.81	STOCK	1,177.81	S
C274-50-133	NUT, CLIP <i>re</i>	12.00	2.36	STOCK	28.32	S
GHP9-50-0Z5	GROMMET, SCREW <i>re</i>	2.00	2.36	STOCK	4.72	S
S51S-51-833	RIVET, SPLASH SHIELD <i>re</i>	8.00	3.12	STOCK	24.96	S
BBM4-50-355	RIVET <i>re</i>	4.00	3.71	STOCK	14.84	S
B45A-56-146A	FASTENER <i>re</i>	2.00	2.36	STOCK	4.72	S
GBVG-50-131	PROTECTOR(L), BUMPER GL3 <i>cut</i>	1.00	79.23	STOCK	79.23	S
GSH7-50-102	COVER LHF BUMPER GL3	1.00	24.87	STOCK	24.87	S
GSH7-50-M42	CAP(L) GL <i>X</i> nn	1.00	73.00	STOCK	73.00	S
F189-51-356A	SPRING <i>X</i> nn	2.00	9.28		18.56	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:
27A Tanjong Penjuru Singapore 609042
Service Tel: 6331 0606
Service Fax: 6331 0620



QUOTATION

CODE: E0139
CUSTOMER: ECICS LIMITED
ADDRESS: 7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

PAGE NO.: 2
DOCUMENT NO.: 2679
DOCUMENT DATE: 04/09/2024
POS ID: 12
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 15568
REF. NO.: DS/SLU1386C/2048
DATE IN: 19/04/2026
EXT. WTY: 0
MILEAGE: 0

CONTACT NO.: 6337 4779
MODEL: MAZDA6 IPM5 2L SDN EXECUTIVE B
CHASSIS NO.: JM6GL1073M0454220
ENGINE NO.: PE21596479
REG NO.: SLU1386C
REGN DATE: 20/04/2021

DESCRIPTION: Body repair

DESCRIPTION: body repair				Qty.	Unit Price	Stk/Status	Gross amount	GST Code
Item	Description				SGD	STOCK	SGD	
GS7-50-104	COVER(L),BUMPER GL3 X nn			1.00	36.50	STOCK	36.50	S
GS7-50-1V0	PLATE(L),SEAL-F.BUMPER GL X nn			1.00	95.25	STOCK	95.25	S
GHP9-50-0U1C	RETAINER LHF BUMPER GJ/GL X nn			1.00	14.84	STOCK	14.84	S
KD47-67-UC5A	RETAINER KF X nn			1.00	15.77	STOCK	15.77	S
KD47-67-UC1	2'SENSOR,ULTRASONIC ?			1.00	184.59	STOCK	184.59	S
GS7-50-7K0D	MOULD LHF LWR BUMPER GL3 X nn			1.00	303.10	STOCK	303.10	S
GS7-50-161	BRACKET LHF BUMPER GL X nn			1.00	44.76	STOCK	44.76	S
GRF5-51-075A	PROTECTOR LHF HL GL3 X nn			1.00	123.15	STOCK	123.15	S
GSK3-51-041B	HEADLAMP LH GL IPM 5 X nn			1.00	5,137.13	STOCK	5,137.13	S
GS7-50-ACYA	BRACKET LHF HL GL3 X nn			1.00	15.77	STOCK	15.77	S
GS7-50-ACXA	BRACKET(L),HEAD LAMP GL3 X nn			1.00	37.01	STOCK	37.01	S
FB01-50-133C	NUT,CLIP X nn			6.00	3.29		19.74	S

	GST Code	Rate	Service/Goods	GST
Parts	7,478.64	O	-	-
Surcharge	0.00	S	9.00%	11,504.64
Labour	4,026.00			1,035.42
Menus	0.00			

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross	11,504.64	1,035.42	12,540.06
Less: Deposit**	0.00	0.00	0.00
Amount Due	11,504.64	1,035.42	12,540.06

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 04/09/2024 13:27 (SGT)
Reported by Both Policyholder and Actual Driver
Date of Accident 03/09/2024 19:03 (SGT)
Exact Location of Accident Singapore
Additional Location Information JUNCTION 10 LEVEL 2 CAR PARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU1386C

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LEE ZONG HAN (LI ZONGHAN)
NRIC No SXXXX856D
Email Address ZONGHAN84@GMAIL.COM
Mobile Phone No (Phone) +65-98584184
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Mazda
Model 6
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1998
Vehicle Fuel -
First Registration Date -
Chassis no -
Effective Date/Time of Ownership -

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number -

DRIVER

1	Z	Name of Driver	LEE ZONG HAN (LI ZONGHAN)
		RIC No	SXXXX856D
		Date Of Birth	25/11/1984
		Occupation	Indoor
2		Driving Pass Date	21/11/2017
3		Driving License Pass Class	3
4		Driving License Validity	Valid
5		Driving experience	6 YEARS AND 10 MONTHS
6		Gender	Male
		Mobile Number	(Phone) +65-98584184
		Alt. Phone Number	-
		Email Address	ZONGHAN84@GMAIL.COM
		Address	442A BUKIT BATOK WEST AVENUE 8 #12-871
		Address complement	-
		Postcode	651442
		Is the driver the policyholder?	Yes
		If No, Relationship of the Driver with the Insured	-
		Does Driver Own Other Vehicles?	No
		Vehicle Registration Number of Other Vehicle Owned by Driver	-
		Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	LEE JIA JUN AIDEN
Gender	Male

PASSENGER 2

Name	GOH PIK WEI
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH8628C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

04/04/24
08:46
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

WHITE HONDA CIVIC SLH8628C REVERSE INTO MY CAR ON SEP 03 AT
07:03 PM AT JUNCTION 10 LEVEL 2 CAR PARK

DRIVER REVERSE CAR TO ALLOW WHITE BMW TO DRIVE OUT OF PARKING LOT
IN ORDER TO OCCUPY THE LOT, WHILE REVERSING, DRIVER DID NOT NOTICE MY
CAR BEHIND.

MINOR IMPACT TO MY CAR AS A RESULT & MY CAR SUFFER 4 PARTIAL DENT AT
THE FRONT BUMPER AREA

EXCHANGED PARTICULARS, NO INJURY

Declaration

We declare the foregoing particulars are true in every respect.

✓  04/09/24
08:49
Policyholder's Signature / Date &
Time

✓ 
Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	856D
Vehicle Details	
Vehicle No.:	SLU1386C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Sep 2024
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT EXECUTIVE I5
Primary Colour:	Grey
Manufacturing Year:	2021
Engine No.:	PE21596479
Chassis No.:	JM6GL1073M0454220
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$22,890.00
Original Registration Date:	20 Apr 2021
First Registration Date:	20 Apr 2021
Transfer Count:	0
Actual ARF Paid:	\$24,046.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Apr 2031
PARF Rebate Amount:	\$18,034.00
Intended COE Rebate Details	
COE Expiry Date:	19 Apr 2031
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$52,200.00
COE Rebate Amount:	\$34,422.00
Total Rebate Amount:	\$52,456.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 15 Sep 2024

OK



Mazda 6 2.0A Executive

\$103,800 Instalment \$1,146/mth

💰 Apply for 2.48% loan

♡ Shortlist

✔ Get Warranty

TRENDING NOW

mycarforum

**Mercedes EV fire burn down
70 cars at Incheon apartm...**

Overview Financial Photo Research

Depreciation	📘 \$14,640 / year
Reg. Date	30-Nov-2020 (6yrs 2mths 14days COE left)
Manufactured	📘 2019
Mileage	83,000 km (21.9k / year)
Transmission	Auto
Engine Cap	1,998 cc
Road Tax	📘 \$1,210 / year
Power	121.0 kW (162 bhp) View specs of the Mazda 6 Sedan (2018)
Curb Weight	📘 1,514 kg
COE	📘 \$39,500
OMV	📘 \$24,127
ARF	📘 \$25,778
Dereg Value	📘 \$43,856 as of today