ASS. REC. BY:	S/SMR24090119/Kvp3
Kenneth	SIGNMENT
From: Date: Estimated Cost: OD ITP WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: at Workshop m/s of 376 Insured: SBS 3974X Policy No. Claims No. BUS/09/24/8005 Sum Insured: Excess:	Veh No: SNE 8044D Yr Regn: C61 15 Type: McCar7 M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailer or Make: Mini One c.c / 198 Colour M. Red A/C: Insured / Std / NI / NA Eng/No: C/No: WMW X S12030 T819270 Gen. Cond: Good/ Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value:	Brake: Inoper / Jammed / Leaked / Burnt or Modi: NII / S/RIm / STD A/RIm or Tyre Size: F: 195/55R/B R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM// TOYO / YOKO or / Cankock Fron! Rear R/Bal.
10/9 1/ Ly @ 2350/ Calil (re	ed 2735.77, 53%)
Date/Time, File Pass to? : Prell. Report Da	ys Of Repair: 2
1)	survey No. of Trip: Survey Fee:
Report Format :	: Site Insp (\$)_S - RSSI : Interview (\$). Fints Tech Invs (\$). Others Weekend (\$
	TOTAL CONTRACTOR OF THE PROPERTY OF THE PROPER

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	376H
Vehicle Details	
Vehicle No.:	SNE8044D
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2024
Vehicle Make:	MINI
Vehicle Model:	ONE 5DR HB 1.2 A/T D/AB ABS DSC
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	F7491022B38A12A
Chassis No.:	WMWXS12030T819270
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$20,163.00
Original Registration Date:	19 Jun 2015
First Registration Date:	19 Jun 2015
Transfer Count:	2
Actual ARF Paid:	\$5,229.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2025
PARF Rebate Amount:	\$2,614.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,000.00
COE Rebate Amount:	\$5,206.00
Total Rebate Amount:	\$7,820.00
Message	
You will not be eligible for any COE rebate from the curr	rent COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 03 Sep 2024

SC1N2493M00C / City Auto Pte Ltd ENTRY DATE & TIME: 03/09/2024 16:38 (SGT) SUBMITTED BY: Jason Quak VERSION: 1 (03/09/2024 16:38 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission Reported by Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

03/09/2024 16:38 (SGT) Actual Driver 03/09/2024 08:50 (SGT) Singapore LIEN YING CHOW DRIVE Singapore

DETAILS OF OWN VEHICLE

Mini

One

Private car

Auto

1200

Vehicle Registration Number

SNE8044D

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner
NRIC No
Email Address
Mobile Phone No
Alternative Phone No

No TAY BEE WAH S1754376H IANTANGL@YAHOO.COM.SG (Phone) +65-96172726

VEHICLE PARTICULARS

Manufacturer Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Vehicle Fuel

First Regisration Date

Chassis no

Effective Date/Time of Ownership

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number WMWXS12030T819270

No - Claiming third party

Income Insurance Limited 5129404641-02

DRIVER



Name of Driver IAN TAN ZHENG LONG NRIC No T0136897J Date Of Birth 30/11/2001 Occupation Indoor Driving Pass Date 12/02/2021 **Driving License Pass Class** 3 **Driving License Validity** Valid Driving experience 3 YEARS AND 7 MONTHS Gender Male Mobile Number (Phone) +65-91994126 Alt. Phone Number **Email Address** IANTANZL@YAHOO.COM.SG Address BLK 157 LORONG 1 TOA PAYOH 09-1239 SINGAPORE 310157 Address complement Postcode 310157 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Child Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface Side Swipe Clear Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

PASSENGER 1

Name Gender JI WOO Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident Yes Yes

WITH OWNER

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

NRIC No

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

SBS3974X

Bus

CHAI CHOI YEONG

S7787841F

(Phone) +65-84812727

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Traffic Police Department for investigation.

- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
 report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

(a) My insurer my workshop and the General Insurance Association of Singapore ("GIA") may are permitted to collect, use, disclose and or process my personal data personal information set out in this [form] and any other personal information provided by metar possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (ail insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers law firms, the Monetary Authority of Singapore and any relevant government agencylauthority (such as the police), for the purpose(s) of:

(i) processing in and inglandion dealing with my claims including the settlement of the dialms and any necessary investigations relating to the dialms.

(ii) investigating the accident and/or my daims;

(iii) carrying out and/or dealing with my instructions or responding to any anguiries by me

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes mail packages), and or

(v) complying with applicable law in administering, processing, handling and or dealing with my claims.

(collectively the "Purposes")

Policyholder's Signature: Date & Time

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers lawyers/law firms, may are permitted to collect, use, disclose under process my Personal Information for one or more of the above Purposes, and


(c) my Personal Information may can be disclosed by any of the Insurers and or GIA to their third-party service providers or agents. (Including their lawyers law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

W Z-

Driver's Signature of driver's not the policyholder. Car-

Witnessed by Reporting Comforth Softmal Name as in NPC/JID part

Sketch Plan



Describe Circumstance of the Accident						
My car was stationary bet	ing copicies duevagade					
to pedestrian crossing shortly after I head a ba a smar bus, was on the les	is and noticed Och B.					
a super bus uses on the let	to ot who cor					
We alighted to sheet &	realised that Veh (B)					
had callided onto my car	1					
the team Maritard cuscar	71"					
No one was injured.						
3						
3P dain @ EM	SOLUTION PTE LTD					
31	160 Sin Ming Autocity					
	Singapore 3/3/22					
Ie Email:	i: 6456 0728 FGC. 6456 mautosolution@singnet.com.30					
Cition						

Declaration

(We seclare the range if a particulars are true in every respect

In

Sould be there a seem on the Control

30


Driversis grature in terver sinutitie policyholder. Date & Imm CITY AUTO PTE LTD Bis a Sin Ming Rhad #01.58/80/62 Sin Ming Ind Est Singapure 575643 Ten 5163 1235 Fox: 6453 7544 (Claims Socilian)

Witnessed by Replieding Sentre Personne Name as in NRIC Libitant

2







E M Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity Singapore 575722 Tel: 64560226

GST/Reg. No: 201016308K

Not Northern ESTIMATE

I My & 2350/ Date: 9th Sept 2024

Runny After Pain Veh No: SNE 8044D

2day, Make/Model: Mini One

Chassis No: WMWXS12030T819

Mdm Tay Bee Wah

Blk 157 Lorong 1 Toa Payoh #09-1239

Singapore 310157

Chassis No: WMWXS12030T819270

Date of Acc: 03.09.24 TP Veh No: SBS 3974X

/No	Qty	Description		Un	Unit Price		Amount		
		Materials			Puller	44 ¢	1	614.60	
1	1 pc	Rear Bumper 1268-70			1010	1 5		284.00	
2	1 pc	Rear Bumper Side Guide LH	6.40		ma	crist		490.00	
3	1 pc	Real Dullipel Love, Car		MEM	493.00	\$		986.00	
4	2 pcs	Rear Lamp L/R C410 Olstux	DIJ -	J c	128.00	\$		256.00	
5	2 pcs	Rear Lamp Chrome Rim L/R Rear Fender Wheel Arch LH 155	7 0	sin	mgo	n15		286.00	
6	1 pc	Rear Fender Wheel Arch LH /55.	20		9	\$	3,	,916.60	
					Less 5%	\$		195.83	
				Р	arts Total	: \$	3	,720.77	
		Special Nett				¢	No	55.00	
1	1 set	Rear Bumper Clips				\$	14	250.00	
2	1 set	Reverse Sensor		Sp	ecial Nett	: \$		305.00	
		Labour				\$		80.00	
1	To remove	e & rearrange electrical wirings, check ligh	tings			Ş		80.00	
2	To remov	e, repair & replace damaged bodyparts, re	ealign bodyw	ork		¢		400.00	
	and wher	e consistent to the accident.				¢		400.00	
3	Putty and	respray painting on affected portions.				\$		80.00	
4	To remov	e & renew reverse sensor				Ś		100.00	
5	Rust proo	fing on affected portions.		Lah	our Total	: \$		1,060.00	
				Lux					
Total Parts & Labo					s & Lahou	r : 5		5,085.77	

for E M Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon

LKK Auto Consultants hence notify

dismantling, we will seek your approval before proceeding. the Repairer of the following:

• To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: