

5b.

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |                                     |                                               |                 |                     |  |
|-------------------------------------------------------------------|-------------------------------------|-----------------------------------------------|-----------------|---------------------|--|
| MS                                                                | MS FIRST CAPITAL                    | INSURANCE LTD                                 | Ref:            | CS/FCI24090124/Uvp3 |  |
|                                                                   | 16 RAFFLES QUAY                     |                                               | Date:           | 24/09/2024          |  |
|                                                                   | #42-01 HONG LEOI<br>SINGAPORE 04858 |                                               | Code:           | FCI2                |  |
| 1.                                                                |                                     |                                               |                 |                     |  |
| •••                                                               | Insured Veh.                        | SHC 1807Y                                     | Veh. Inspected  | SJS 1818H           |  |
|                                                                   | Policy No.                          | D-24101861MFCT                                | Coverage        | 0                   |  |
|                                                                   | Claim No.                           | D24007841MFCT                                 | Excess          | \$0.00              |  |
|                                                                   | Assign From                         | JOANNE                                        | Assign Date     | 06/09/2024          |  |
| 2.                                                                |                                     |                                               |                 |                     |  |
|                                                                   | Make & Model                        | TOYOTA ALPHARD (A)                            | c.c             | 2493                |  |
|                                                                   | Engine No.                          | 2ARH630682                                    | Year of Reg.    | 18/07/2016          |  |
|                                                                   | Chassis No.                         | AGH300038932                                  | Colour          | BLACK               |  |
|                                                                   | Odometer                            | 367687 KM                                     | Steering        | IN ORDER            |  |
|                                                                   | Brakes                              | IN ORDER                                      | General         | GOOD                |  |
|                                                                   | Modification(s)                     | RIMS: SPORTS RIM                              | •               |                     |  |
| 3. Conditions of Tyres                                            |                                     |                                               |                 |                     |  |
|                                                                   |                                     | Size                                          | Make            | Balance (mm)        |  |
|                                                                   | R/H Front Tyre                      | 245/45R19                                     | TRIANGLE        | 7                   |  |
|                                                                   | L/H Front Tyre                      | 245/45R19                                     | TRIANGLE        | 7                   |  |
|                                                                   | R/H Rear Tyre                       | 235/50R19                                     | PIRELLI         | 7                   |  |
|                                                                   | L/H Rear Tyre                       | 235/50R19                                     | PIRELLI         | 7                   |  |
| 4. Description of Damages                                         |                                     |                                               |                 |                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.                |                                     |                                               |                 |                     |  |
| DAMAGES SEE DETAILS.                                              |                                     |                                               |                 |                     |  |
| 5. General Information                                            |                                     |                                               |                 |                     |  |
|                                                                   | Accident Date                       | 05/09/2024                                    | Inspection Date | 10/09/2024          |  |
|                                                                   | Survey held at                      | FASTECH AUTO PTE LTD                          | -               |                     |  |
|                                                                   |                                     | 1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY |                 |                     |  |
|                                                                   |                                     | SINGAPORE 417883                              |                 |                     |  |
| 5a. Remarks                                                       |                                     |                                               |                 |                     |  |
| A) D                                                              |                                     | ENT TO ACCIDENT REPORT.                       |                 |                     |  |

**Estimate Days of Repair** 

B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.