ASS. REC. BY:	124090127/RUP3 307R
SO. Had at the second of the s	ASSIGNMENT
From: Estimated Cost: OD/TP/WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No: GBM 4386K at Workshop m/s CYLL of Insured: Policy No. Claims No. Sum Insured: (Client's Record) Make of Veh:	Veh No: 48M 4389K Yr Regn: 222 1565 Type: M.Car / M.Cycle / Bus Wan/ Lorry / Taxi / Prime Mover / Truck / Trailer or Make: MCLCON MALEVITO 112 L c.c Colour WHIRL AC: Insured / Std / Ni / NA Sp.Reading 2089 T/Radio: Insured / Std / Ni / NA Eng/No: C/No: W 1/44 760 32 4208454 Gen. Cond: Good Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nii / S/Rim / STD A/Rim or Tyre Size: F: 225/55781
(Policy Condition)	R: R: O/S RS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Remark: The veh had commenced its repair at the time of inspection.	TOYO / YOKO or KWYY
Bal. or Market Value: 1201	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	7
GIA / PR Seen: Consistent?: Yes or No	
Est. Repairs: days Res.: Yes or No	· · · · · · · · · · · · · · · · · · ·
Lum Sum: % 3 Val.: Yes or No	
CA I REV I REP. I 24HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Data / Time Action / Instruction	,
REPAIR LIMIT-45K	
	· · · · · · · · · · · · · · · · · · ·
Date/Time, File Pass to? Preli. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Raturn to?	Transportation:
2)	Add Fee: Site Insp (\$)s+R6Si
	: Interview (\$); Photos

:Tech. Invs (\$

:Weekend (\$

TOTAL

Report Format:

Lump Sum / I.B.I: (\$



Company Reg No. 196400304H GST Reg No. MR-8500111-X

STIMATE

Invoice Name & Address

Mobile: 91185739

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte Ltd

239 ALEXANDRA ROAD

Singapore 159930 159930

Contact No

Reg No/Reg Date

GBM4389K

/ 15/09/2023

Date In/Mileage

10/09/2024/

30899

Chassis No

*W1V44760324208454

Engine No

Make/Model

EVITO 112 LONG AT

Acco	unt No	Terms	Date/Time Prin	ted	CSE	Operator			WIP No		
CSMO	0061	Cash	10/09/2024/	11:26	TLL	1210/ Lim	Teng Keat		33451		
			Descriptio	n of Good	s / Services			Qty	Unit Price	Disc%	Amount
1	TEXT TP CLAIM DOA 03/09 SUR LKK	/2024	CAPITAL	4							
E		CE FRT BU	/ MPER, FRT LHS NT AFFECTED A		HEADLAMP						for 1350.0
E	PNT98000		BUMPER, FRT I	/	/ NED EDT 1 US	DOOD					200 1600.0
M	SUNDRY ANTI-RUS			LIIS FEMU	ICR, FRI LMS						60 160.0
M	SUNDRY		T ON AFFECTED	ADEA							60 160.0
A	WHEELALI	GNMENT120)L	DAMPS CONTRACTOR							× 250.0
A	54900099		terize Full Who								(UD 200.0
A	10028901		CHASSIS ELECTR								280 386.0
	SUNDRY	OUT DIAG	GNOSTIC CHECK (ON ELECT	RONIC CONTR	OL SYSTEM					20 86.0
M	SUNDRIES SUNDRY TRIM, BUI FRT BUMP	MPER 2 1.									2440.4
	SUNDRY										158.9
	REINFORCE FRT BUMP		IMPER 37								100.3
	SUNDRY COVER		7								58.8
	FRT BUMP SUNDRY MOUNTING		ILLE -								79.3

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring



Company Reg No. 196400304H GST Reg No. MR-8500111-X

TIMATE

Invoice Name & Address

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte Ltd

Mobile: 91185739

•

239 ALEXANDRA ROAD

Singapore 159930

159930

Contact No

Reg No/Reg Date Date In/Mileage GBM4389K / 15/09/2023

Chassis No

10/09/2024/ 30899

Camban Ma

*W1V44760324208454

Engine No

Make/Model

EVITO 112 LONG AT

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
CSM00061	Cash	10/09/2024/ 11	:26 TLL	1210/ Lim Teng Keat		33451		
			Goods / Services		Qty	Unit Price	Disc%	Amount
M SUNDRY BRACIN	G .	NDER STAY CM	_					32.00
SUNDRY ELECTR		HARNESS 7	•					31.1
SUNDRY CENTRAL	LOCKING M							94.9
SUNDRY BUTTON	SWITCH	NING AND CLOSE SI		lmat				106.7
SUNDRY COUPLI	NG, MECHANI	CAL 27	VIICH					48.0
SUNDRY CLUTCH	HOUSING	HOUSING 7.						15.2
SUNDRY ELECTRI		HARNESS 37						413.6
SUNDRY								795.4
SUNDRY	FRONT Lu	_						899.1
SUNDRY	ULAR BOLT *	5 PCS Ren/y						36.0
SUNDRY HOLDER	FENDER COV	FR HOLDER						9.6

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Company Reg No. 196400304H GST Reg No. MR-8500111-X

TIMATE

Invoice Name & Address

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte Ltd

239 ALEXANDRA ROAD

Singapore 159930

159930

Contact No

Mobile: 91185739

Reg No/Reg Date

GBM4389K

/ 15/09/2023

Date In/Mileage

10/09/2024/ 30899

Chassis No

*W1V44760324208454

Engine No

Make/Model

EVITO 112 LONG AT

Account No	Terms	Date/Time Prin	ted	CSE	Operator			WIP No		Of great congressions
CSM00061	Cash	10/09/2024/	11:26	TLL	1210/ Lim	Teng Keat		33451		
		Descriptio	n of Goods /	Services			Qty	Unit Price	Disc%	Amount
M SUNDRY INTERMED FRT LHS	IATE LAYE FENDER FO	R AM LAYER LAW.	/							16.00
M SUNDRY		NG IEEL HOUSE COVE	R)cm/	•						178.68
M SUNDRY EXPANSION		5 PCS Ine								80.00
M SUNDRY PLASTIC FRT LHS	NUT FENDER WH	HEEL HOUSE COVE	R CLIP Ne							96.00
CROSSMEN		37				OL				1120.02
M SUNDRY CARRIER HEADLAM	PANEL 3	7								472.74
M SUNDRY HOLDER HOLDER 1	OR RADAR	SENSOR BRACKET	٦ ⁷ .							50.00
M SUNDRY HOLDER HOLDER I	OR LHS MO	DDULE 77								81.46
M SUNDRY BUMPER I	OLDER	RT HOLDER 7.								63.58
M SUNDRY LINK BLO		37								21.46
M SUNDRY LINK BLO	3 -									30.00
M SUNDRY	1.									77.91

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after recording the second of the required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replairs or repairs work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replairs or replain to repair and the repair work has started and needed for repairs or replain to repair and the repair work has started and needed for repairs or replain to repair work has started and needed for repairs or replain to repair work has started and needed for repairs or replain to repair work has started and needed for repairs or replain to repair work has started and needed for repairs or replain to repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs or repair work has started and needed for repairs would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also support the payable payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also support the public seal or other repair requir cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the removal of the windscreen.



Company Reg No. 196400304H GST Reg No. MR-8500111-X

STIMATE

Invoice Name & Address

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte Ltd

Reg No/Reg Date

GBM4389K

/ 15/09/2023

239 ALEXANDRA ROAD

Date In/Mileage

10/09/2024/

30899

Singapore 159930

Chassis No

*W1V44760324208454

159930

Engine No

Contact No

Mobile: 91185739

Make/Model

EVITO 112 LONG AT

	Terms	Date/Time Prin	nted	CSE	Operator	WIP No		
CSM00061	Cash	10/09/2024/	11:26	TLL	1210/ Lim Teng Keat	33451		
		Description	on of Goods	/ Services	Qty	Unit Price	Disc%	Amount
		OTOR 37	SURVEYO	LKK/ the R • To re • To di • Parts • Third • No ii	Auto Consultants hence notify epairer of the following: survey before/after spray pointing splay demaged part(s) during resurvey a prices are subject to confirmation it party survey is on a "Without Prejudice" basis legal modification(s) is allowed bleen and interest term(s) must be resurveyed and bleet to final approval from Insurance Company wiledged by Repairer hire:	Unitrince		300.8

Confirm & accepted by

Nett

11,988.23

9% GST on

11988.23

1078.94

Total Payable

13,067.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST, We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after more and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you place the control of the cont would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also seven the work. Payment for this may be made in cash, credit card or cheque. You must also seven the work. Payment for this may be made in cash, credit card or cheque. You must also seven the work. Payment for this may be made in cash, credit card or cheque. You must also seven the work of the wor cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the removal of the windscreen.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

/ehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	307R
/ehicle Details	
/ehicle No.:	GBM4389K
/ehicle to be Exported:	No
ntended Deregistration Date:	12 Sep 2024
/ehicle Make:	MERCEDES BENZ
/ehicle Model:	EVITO 112 LONG AT
Primary Colour:	White
Manufacturing Year:	2022
ingine No.:	•
Chassis No.:	W1V44760324208454
Maximum Power Output:	
Open Market Value:	\$58,472.00
Original Registration Date:	15 Sep 2023
irst Registration Date:	15 Sep 2023
ransfer Count:	0
Actual ARF Paid:	\$2,924.00
ntended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	.5:
PARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
COE Expiry Date:	14 Sep 2033
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$82,889.00
COE Rebate Amount:	\$74,646.00
otal Rebate Amount:	\$74,646.00
Message	

The information contained herein is correct as at 11 Sep 2024

m.sgcarmart.com













Mercedes-Benz eVito Electric 112 Long

\$128,800 Instalment \$1,697/mth

PREMIUM AD



C Shortlist

☐ Loan Calculator









Overview Financial Photo Research

Depreciation

(i) \$13,370 / year

i 29-Apr-2044

30-Apr-2024 (9yrs 7mths 18days COE left)

Reg. Date

① 2022

Manufactured

Lifespan

Mileage

Transmission Auto

Curb Weight

① 2,300 kg

Fuel Type

Electric

Drive Range

COE

\$22,718 (i) \$59,508

(i) 1

ARF

OMV

\$2,976 (i) \$18,174 as of today

Dereg Value No. of Owners