

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS/INC24090135/Aqh3m4(N)	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557	Date:	17/01/2025	
	ATTN: FIONA SHE	N	Code	: INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 4783L	Veh. Inspected	SNA 9726J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1294052-002	Excess (\$)	0.00	
	Assign From	JURAIDAH ABBAS	Assign Date	09/09/2024	
2. Vehicle Particulars & Condition					
	Make & Model	BMW X1	c.c	1499	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	WBAJG12070EN53781	Colour	BRONZE	
	Odometer	82773 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/50R18	PIRELLI	6 mm	
	L/H Front Tyre	225/50R18	PIRELLI	6 mm	
	R/H Rear Tyre	225/50R18	PIRELLI	6 mm	
	L/H Rear Tyre	225/50R18	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	06/09/2024	Inspect Date / Time	09/09/2024 ( 11:57 AM )	
	Survey held at	RYDER AUTO PTE LTD			
		2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	8 Wo	king Days	
	-				