

REF:

ASSIGNMENT

From: _____ Date: _____

Estim: ~~Estim~~OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MVTo In ~~Vehicle~~ No: _____at W ~~Work~~ / m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Vehicle _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMN4281B Yr Regn: 2019, Augst.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Land Cruiser CO 4608Colour: Black A/C: Insured / Std / NI / NASp. Reading: 47197 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: URJ2024187615Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/60R18R: 285/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 28/08/24Survey held at YSKDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time _____ Action / Instruction

TPALGCOE ExpiryEstimate given during : Yes ()
1st Survey : No (✓)

MV :

PV :

Nett :

064Z.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

Report Format: _____

Report Date: _____