

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	28/05/2024 10:49 (SGT)
Reported by	Actual Driver
Date of Accident	19/05/2024 18:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CHANGI AIRPORT T3 LEVEL 2 CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT9920M
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BEN FOODS (S) PTE LTD
Company Reg No	196900017H
Email Address	mlee@benfoods.com
Mobile Phone No	(Phone) +65-96315968
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	2360

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	B 400002626 MCY

DRIVER

Name of Driver	LEE KOK THYE
NRIC No	S1267290Z
Date Of Birth	16/06/1957
Occupation	Indoor

Driving Pass Date	15/05/1980
Driving experience	44 YEARS
Gender	Male
Mobile Number	(Phone) +65-96315968
Alt. Phone Number	-
Email Address	mlee@benfoods.com
Address	44 BINCHANG RISE
Address complement	-
Postcode	579909
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	6
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	WIFE
Gender	Female

PASSENGER 2

Name	DAUGHTER
Gender	Female

PASSENGER 3

Name	SON IN LAW
Gender	Male

PASSENGER 4

Name	GRANDCHILD
Gender	Male

PASSENGER 5

Name	GRANDCHILD
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

REFER SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLB7964U
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan

Describe Circumstances of the Accident

Refn attached

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

27 May 2024

Dear Sir

RE: ACCIDENT REPORT FOR VEHICLE: SLT 9920M

DATE OF ACCIDENT: 19/5/24 (SUNDAY)

1. Accident happened on Sunday, 19/5/24 at about 6:00pm in Changi airport Terminal 3 car park level 2.
I was reversing my car (SLT 9920M) very slowly and bumped on the car behind (SLB 7964U)
2. I immediately stopped and the other driver (Mr KH Lim), and I thoroughly inspected our cars, as there showed no damages. We went on our separate way and parked our car.
3. As I was going up the lift to check into my flight, Mr KH Lim and his family saw me and requested that I go to the car park as there were marks on his car bumper after thoroughly checking his car.
4. I agreed to go with them and we thoroughly checked the front bumper and we found a small marking on his bumper (see photographs A & A1).
5. Mr KH Lim and I agreed that was the only damaged and my wife took a picture of the car as a proof (see photographs B & B1).
6. Since I was leaving the country and have no time to furnish an accident report, I proposed to Mr KH Lim to send his car to the workshop and I will pay for the cost of the repair works on the part of the bumper that we both had agreed (see photographs A & A1).
7. We exchanged particulars and phone number and Mr KH Lim whatsapp me on the cost of the repair.
I have checked and replied him and he agreed that his mechanic also charged the same amount (please see photographs C, C1, C2, C3 & C4).
8. After a few days he sent me whatsapp informing me of further damages to his car lower bumper and also informed me that he had done an accident report (see photograph D and whatsapp messages).
9. In conclusion, the facts are:-
 - a) After the accidents, Mr KH Lim and family members had several times thoroughly checked the vehicle and could only find the small marks on the front bumper (see photographs A & A1).
 - b) The pictures taken of the car, together with the enlarge picture of the parts showed the actual condition of the bumper at the time of the accident, (see photo B & B1)

- c) Both of us agreed that there no other damages other then the small mark on the front bumper (Photo A & A1).
- d) The damages that Mr KH Lim later established (see photograph D) are too obviously and cannot be missed since he together with his family had done several thorough checks on his vehicle after the incident.
- e) This can be verified by the photographs of the vehicle taken on the day of the accident by my wife, showing that the rest of the front bumper was in good condition (see photograph B & B1).
- f) Since I only returned on Sunday, 26/5/24, I can only make an accident report on Monday 27/5/24 (see air ticket attached).

Please feel free to contact me if further information is required.

Appreciate your investigation on the above accident.

Thank you

Reported by:



Lee Kok Thye

S1267290/Z

Vehicle SLT 9920M











Michael

5/25/2024 at 8:10 AM

PHOTO A



PHOTO A1



PHOTO B



PHOTO B1




PHOTO C1



PHOTO C




PHOTO C2



PHOTO C3



PHOTO C4



PHOTO D

