

MOTOR SURVEY ASSIGNMENT

Date	19/06/2024	Our Ref No.	D24005382MFCT
Accident Date	18-06-2024	Claim Type	Third Party
Insured Vehicle	SH8813B	Third Party Vehicle	SNE8488G

Survey Location	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD (S) 159934	Contact Person	MEIYU WONG
------------------------	---	-----------------------	------------

Contact No.	81214681	Fax No.	
--------------------	----------	----------------	--

Survey Type Direct Settlement
(quantum to be agreed)

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person		Fax No.	68416315
-----------------------	--	----------------	----------

Contact Number 62563561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & Estimate

Cc : Workshop VOLKSWAGEN GROUP SINGAPORE PTE LTD **Attention** MEIYU WONG
Officer Incharge NEOJIE

IMPORTANT NOTE

Kindly submit the survey report by **email only** to surveyor@msfirstcapital.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.