



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: BETTY			Ref: CS/FCI24090170/Avp3e2(N) Date: 27/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 703U	Veh. Inspected	EU 8810G	
Policy No.	D-24101860MFCT	Coverage (\$)	0.00	
Claim No.	D24007627MFCT	Excess (\$)	0.00	
Assign From	BETTY	Assign Date	09/09/2024	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO FORTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KNAFW411MA5290570	Colour	GREY	
Odometer	200313 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/45 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/08/2024	Inspection Date	10/09/2024	
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		