



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS GREAT AMERICAN INSURANCE COMPANY	Ref:	CS/GAI24090184/Rvp3e2
3 TEMASEK AVENUE	Date:	11/11/2024
#16-01 CENTENNIAL TOWER	Code:	GAI
SINGAPORE 039190		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 8938G	Veh. Inspected	SLQ 6918G
Policy No.	-	Coverage	0
Claim No.	CLMOMVC000004539	Excess	\$0.00
Assign From	JASMINE	Assign Date	11/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E200	C.C	1991
Engine No.	27492030812909	Year of Reg.	19/07/2017
Chassis No.	WDD2130422A102583	Colour	BLACK
Odometer	129689 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55 R17	CONTINENTAL	6
L/H Front Tyre	225/55 R17	CONTINENTAL	6
R/H Rear Tyre	225/55 R17	CONTINENTAL	6
L/H Rear Tyre	225/55 R17	CONTINENTAL	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/09/2024	Inspection Date	08/10/2024
Survey held at	DIPLOMAT PARTS PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days