

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547727
FAX :

Date : 11/09/2024
To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 05/09/2024
Vehicle No : GBM-2293-R Make & Model : BYD T3 ELECTRIC PANEL VAN G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BUMPER <i>repair</i>	1,230.00	
1	REAR BUMPER RETAINER LH <i>X1</i>	89.00	
	Sub Total	1319.00	
	Discount 10% On Parts	(131.90)	

Labour & Misc

	LABOUR TO FACILITATE REPAIR	250 300.00	<i>500</i>
	TO RESPRAY AFFECTED AREAS	250 300.00	

Date : 11/09/2024
 To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : 1 Accident Date : 05/09/2024
 Vehicle No : GBM-2293-R Make & Model : BYD T3 ELECTRIC PANEL VAN G (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Sub Total

600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1,787.10

Remarks:

2 days / P/P

SUB TOTAL
 GST 9.0 % 160.84
 TOTAL 1,947.94

Surveyor's name: Rasul - Hp 900 100 638

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 11/09/24
Resy after repair