REF:

## CTI CS/CTI24090204/Enh3e2 (SHB 1314H)

## ASSIGNMENT

From: Date:	Veh No: SHB 1314H Yr Regn: 28/11//2017
	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Prius c.c 1797
	Colour Maroon A/C: Insured / Std / NI / NA
	Sp.Reading 566010 T/Radio: Insured / Std / NI / NA
The state of the s	Eng/No:
Policy No.	C/No: JTDKB3FU403573724 *
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 195/65R15
(Policy Condition)	R: "
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or WESTLAKE
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 07/09/24 D.O.I. 10/09/24
Lum Sum: % 3 Val.: Yes or No	Survey held at Strides Premier Automotive
A AND DESCRIPTION OF THE PROPERTY OF THE PROPE	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS  Vehicle: IN / OU	Т
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
We finalize \$456.00 (P/P, bef	ore CST) 2 days
(red, \$8143.6, 94%)	ore Got). 2 days.
(led, \$6143.0, 9476)	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 2
	Resurvey No. of Trip: Survey Fee:
Final Report	Resurvey No. of Trip:
1) : Final Report  Date/Time, File Return to?	Resurvey No. of Trip:  Survey Fee:  Transportation:
Date/Time, File Return to?	Transportation:
Date/Time, File Return to?	Transportation:
Date/Time, File Return to?  Add F	Transportation:
Date/Time, File Return to?	Transportation: