

# SMRT Accident Vehicle Repair Estimates

SMRT Autor  
60 Woodlanc  
FAX Number  
Estimator Te  
Accident Rep

Date Genera  
User ID

China Taiping

## Section A - Accident Details

Registration Number	SHB1314H
Case Reference Number	TAX/09/24/2015
Registration Date	28/11/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHEN CHON LIANG (CHEN JUNLIANG)
Type of Accident	Head to Rear
Accident Date and Time	7/9/2024 2:00 AM
Accident Reported Date and Time	9/9/2024 9:01 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24122378
Special Instruction to ARC, if any	DAMAGE TO THE FRONT PORTION OF TAXI - TOWED IN
Prepared Date and Time	9/9/2024 9:22 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

## Section B - Summary of Repair Estimates

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$0.00
Total Spray Cost	\$378.00	\$0.00
Total Spare Part Cost	\$3,667.75	\$0.00
Total Other Cost	\$436.00	\$0.00
<b>TOTAL COST</b>	<b>\$5,157.75</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$5,150.00</b>	<b>\$0.00</b>
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	09/09/2024 9:31 AM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Steve C (KK)  
10/9/24, 4.30pm

PIP (m part gily)  
Ly AL 14

## Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

**SMRT Accident Vehicle Repair Estimates**

SMRT Author  
60 Woodlark  
FAX Number  
Estimator Te  
Accident Re

Date Genera

User ID

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR FRONT PORTION	\$676.00	209
<b>Total Labour</b>	<b>\$676.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY FRONT BUMPER	\$378.00	200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$378.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TOWING CHARGE	\$56.00	-X- / Nec
TO WASH AND VACUUM	\$60.00	X nn
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	X nn
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	X nn
TO REPLACE SUNDRY PARTS	\$100.00	X nn
<b>Total Other Costs</b>	<b>\$436.00</b>	

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		5311247240	GRILLE, RADIATOR	1.00	\$183.90	25.00	\$137.93	Replace	X nn
		5310147080	GRILLE SUB-ASSY	1.00	\$374.40	25.00	\$280.80	Replace	X nn
		5216116010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	X nn
		8122047020	LAMP ASSY, FOG, LH	1.00	\$1,029.90	25.00	\$772.43	Replace	X nn
		8118547691	UNIT, HEADLAMP, LH	1.00	\$2,852.40	25.00	\$2,139.30	Replace	X nn
		8105647690	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$1,039.90	25.00	\$779.93	Replace	X nn
		5261147140	ABSORBER, FR BUMPER	1.00	\$85.90	25.00	\$64.43	Replace	X nn
		5202147110	REINFORCEMENT FRONT UPPER	1.00	\$773.90	25.00	\$580.43	Replace	X nn
		5212847906	COVER, FR BUMPER LH	1.00	\$31.80	25.00	\$23.85	Replace	X R
		5211647050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	X nn
		5211547050	SUPPORT, FR BUMPER RH	1.00	\$86.20	25.00	\$64.65	Replace	X nn
		5211947962	COVER, FR BUMPER	1.00	\$560.30	25.00	\$420.22	Replace	X R
<b>Total</b>					<b>\$7,109.60</b>		<b>\$5,364.62</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor CI
<b>Total</b>									