

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	LIBERTY INSURAN	CE PTE LTD	Ref:	CS3/LIP24090205/Enh3e2
	ONE RAFFLES QUA SINGAPORE 04858	AY #25-01 NORTH TOWER	Date:	12/09/2024
	01140741 OTTE 04000		Code:	LIP
1. Policy Particulars :- PRE-RE				EY
	Insured Veh.	SNN 2027X	Veh. Inspected	FBK 763A
	Policy No.	-	Coverage	0
	Claim No.	AVS24/2732	Excess	\$0.00
	Assign From	TED	Assign Date	09/09/2024
2. Vehicle Details				
	Make & Model	HONDA CBR150R	C.C	150
	Engine No.	KC178E0408500	Year of Reg.	12/03/2015
	Chassis No.	MLHKC1786F5408500	Colour	WHITE
	Odometer	213496 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
1				
	R/H Front Tyre	110/70-17	PIRELLI	5
	R/H Front Tyre L/H Front Tyre	110/70-17	PIRELLI	5
		110/70-17 140/70-17	PIRELLI PIRELLI	5
	L/H Front Tyre			
4.	L/H Front Tyre R/H Rear Tyre		PIRELLI	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	140/70-17	PIRELLI of Damages	5
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	140/70-17  Description of	PIRELLI  of Damages  ON AND O/S BODY	5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	140/70-17  Description of the Damages at the Front Portion of the Damages at the the	PIRELLI  of Damages  ON AND O/S BODY	5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	140/70-17  Description of the DAMAGES AT THE FRONT PORTION General Info	PIRELLI  of Damages  ON AND O/S BODY  formation  Inspection Date	5 
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	Description of Descri	PIRELLI  of Damages  ON AND O/S BODY formation Inspection Date  EMIUM 61 WOODL	5 '. '. '. '. '.
5a. A)M. B) T C) T THE D) E	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAINI  Accident Date Survey held at  ARKET VALUE: \$2,888 HE INSPECTION WAS TO NCLOSED PLEASE	Description of Description of Description of DAMAGES AT THE FRONT PORTION General Into 02/09/2024  ERZAT LEE TYRES PTE LTD - E9 PR SINGAPORE 757047	PIRELLI  of Damages  ON AND O/S BODY formation Inspection Date EMIUM 61 WOODL  arks ALUE: \$569.00=NE EJUDICE" BASIS. ME OF INSPECTICE  APHS.	5 09/09/2024 (13:14) ANDS INDUSTRIAL PARK E9 #01-13 TT VALUE: \$2,231.00
5a. A)M. B) T C) T THE D) E	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAINI  Accident Date Survey held at  ARKET VALUE: \$2,888 HE INSPECTION WAS TO NCLOSED PLEASE	Description of Descri	PIRELLI  of Damages  ON AND O/S BODY  formation  Inspection Date  EMIUM 61 WOODL  arks  ALUE: \$569.00=NE  EJUDICE" BASIS.  ME OF INSPECTION  APHS.  LE IS IN THE REG	5 09/09/2024 (13:14) ANDS INDUSTRIAL PARK E9 #01-13 TT VALUE: \$2,231.00

CTY

STEVE CHEN TSUE YEE