Surveyor:	REF: CS/I	_AW24090208/Dnp3 (FBT 9383G	) Special Instruction:
ASSIGNMENT (Office) From (Person): JEAN ONG of TAN CHIN & HO Date/Time: 11/09/2024 Estimated Cost: Bill to:			L/SUM: 2550 / REPAIR: 3 DAYS
			Third Parties:
			Claimant:
			Surveyor: CL APPRAISER PTE L
OD/TP Re-inspection / Evaluation To Inspect Vehicle No: FBT 9383G Insured: SLK 1243.1			Workshop: BLACK INDUSTRY
		Insured:SLK 1243.	]
600	LACK INDUSTRY ROAD 4 #01-43 SYNERGY	Tel:	_
Compression and the second			
olicy No:		Claim No: _ RT/JR/5/20	24/JO
um Insured:		Excess:	***************************************
Make of Veh: Client's Record)		D.O.A. <u>30/05/2023</u>	
Date/Time:	Person Contact	ed: Vehicle IN / O	H.O.D. Endorsement/Date:
Date/Time:	Confirmed with	venicle IN/U	01
Date/Time: 06/11	24 Submit Final Fig. 300	0, 3 days (Red \$2100	(Red \$/_%; Originaldays)
		5 days (Red \$2100	/41%; Original 3 days)
Action	/Instruction		
	***************************************		
Para(1) · Parta	ound not		
(a, a(1) . 1 al (5)	ound not replaced (	To highlight R or UB,	LR, Etc)
·			
Para(2) · Comm	ents on consist		
(2): Comm	ents on consistency of	f damages (Parts Not Consi	stent: NC)
Para(3): Nett V	alue		
Mark	et Value :	Inspected/	Fee Charged: Date:
1			Basic & Add Transport
Salva	ge Value:		Photos
Nett	Value :		Others
0.70	File Pass to	) D	Total
3) Date/Time			File Return to
	File Pass toFile Pass to		
,	rile Pass to	6) Date/Time	File Return to