SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 18/06/2024 17:03 (SGT) Reported by **Actual Driver** Date of Accident 17/06/2024 14:47 (SGT) Exact Location of Accident 512 Tampines Central 1, Singapore 520512 Additional Location Information TAMPINES BUS INTERCHANGE Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Alexander Dennis

Vehicle Registration Number SG6367R

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner TOWER TRANSIT SINGAPORE PTE LTD Company Reg No 2XXXXX417K Email Address feedback@towertransit.sg Mobile Phone No (Phone) +65-18002480950 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model ENVIRO500 Variant DOUBLE DECKER Exact purpose for which vehicle was being used at time of accident **Employment** Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Bus Transmission Auto CC 10000

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd Policy Number / Cover Note Number D-24102356MFBP

DRIVER

Name of Driver **TOH JIA HAUR** Work Permit No GXXXX390W Date Of Birth Occupation Outdoor

Driving Pass Date 26/03/2015 Driving experience 9 YEARS AND 3 MONTHS Gender Mobile Number (Phone) +65-18002480950 Alt. Phone Number Email Address feedback@towertransit.sg Address C/O: 21 BULIM DRIVE Address complement **BULIM BUS DEPOT** Postcode 648170 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Side Swipe Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SG5816T Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour

Bus

Vehicle Category

Name of Driver
Contact Number

Address		<u>-</u>
Address complement		
Postcode		
Insurance Company Name		-
Nature Of Damage		
Details of property damaged in accident	 	
No. Of Passenger (Including Driver)	 	

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



SINGA


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

SINGAL

Driver's Signature (if driver is not the policyholder) / Dat & Time Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



1

Describe Circumstance of the Accident			
& Please re	efer to	statement &	
Alles	1) 1- 0 \ \/	
Tr.			

Declaration

I/We declare the foregoing particulars are true in every respect.



MOI + Corporative / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Perso (Name as in NRIC/ID card)

2



Statement Form

Employee Name	Toh Jia Huar	Employee ID	14255
Designation	ВС	Date Taken	17/06/2024
Service No	969	Time Taken	1610hrs
Bus Registration No	SG6367R	Date of Incident	17/06/2024
Duty Number	969A06	Time of Incident	1445hrs
Nature of Incident	Accident with SMRT S	vc 67 at Tampines Interchange	

I BC Toh (14255) while my bus is stationary in the parking lot, however SMRT svc 67 was reversing and hit my bus right rear blind spot camera.

Damage:

TTS sustained right rear blind spot camera dislodged.

SMRT sustained left rear blind spot sensor dislodged.

My bus is equipped with 360-degree cameras and in operation at time of incident.

Details:

*I confirmed that the above statement given by me is correct to the best of my knowledge.

Employee Name and ID

Signature

Date & Time

Statement Taken By:

Employee Name and ID

____Interchange Supervisor

Signature

Designation

Page 1 of 1





