



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090238/Uvp3
16 RAFFLES QUAY	Date:	02/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 619E	Veh. Inspected	SNL 8688J
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24007937MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	13/09/2024

2. Vehicle Details

Make & Model	HONDA VEZEL (A)	C.C	1496
Engine No.	LEC1005279	Year of Reg.	28/03/2023
Chassis No.	RV51004350	Colour	WHITE
Odometer	107981 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	VIKING	7
L/H Front Tyre	215/60R16	VIKING	7
R/H Rear Tyre	215/60R16	VIKING	7
L/H Rear Tyre	215/60R16	VIKING	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/09/2024	Inspection Date	17/09/2024
Survey held at	WE GARAGE - 1 KAKI BUKIT AVE 6, #02-11 AUTOBAY @ KAKI BUKIT, SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days