

MOTOR SURVEY ASSIGNMENT

Date 13/09/2024 **Our Ref No.** D24007997MFCT

Accident Date 11-09-2024 Claim Type Third Party

Insured Vehicle SH8958S Third Party Vehicle SMZ5629M

Survey Location KAH MOTOR CO. SDN. BHD. Contact Person NG SIN HAI 9072176!

BODY REPAIR & PAINT CENTRE

8 MANDAI ESTATE (S) 729905

Contact No. 65145266 **Fax No.** 63651949

Survey Type Without Prejudice - No video providedm,

surveyor to check damage consistency.

Appointed LKK AUTO CONSULTANTS PTE LTD

Surveyor

Contact Person Fax No. 68416315

Contact Number 62563561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & Estimate

Cc: Workshop KAH MOTOR CO. SDN. BHD. Attention NG SIN HAI 90721769

Officer Incharge JASONTEA

IMPORTANT NOTE

Kindly submit the survey report by **email only** to <u>surveyor@msfirstcapital.com.sg</u> within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.