



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY #21-01
SGX CENTRE 2 SINGAPORE 068807

Ref: CS/MSG24060163/Kqh3e2

Date: 20/06/2024

Code: MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLICLIABILITY	Veh. Inspected	GBL 5265H
Policy No.	-	Coverage	0
Claim No.	363244	Excess	\$0.00
Assign From	LIM AI KIM	Assign Date	20/06/2024

2. Vehicle Details

Make & Model	TOYOTA TOWN ACE GL (A)	C.C	1496
Engine No.	2NRG624592	Year of Reg.	01/10/2021
Chassis No.	S403M0005189	Colour	WHITE
Odometer	114557 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/70R14	KAPSEN	9
L/H Front Tyre	175/70R14	KAPSEN	9
R/H Rear Tyre	175/70R14	KAPSEN	9
L/H Rear Tyre	175/70R14	KAPSEN	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/06/2024	Inspection Date	24/06/2024
Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days