



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924		Ref: Date: Code:	CS/AGI24090272/Knp3m4 27/09/2024 AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFC 7929M	Veh. Inspected	SMP 7601G	
Policy No.	P10192532R05	Coverage	0	
Claim No.	C10031680/KY	Excess	\$0.00	
Assign From	JUSTIN WONG	Assign Date	16/09/2024	
2. Vehicle Details				
Make & Model	HONDA SHUTTLE HYBRID 1.5 AUTO	C.C	1496	
Engine No.	LEB7105348	Year of Reg.	15/10/2019	
Chassis No.	GP72004141	Colour	METALLIC BLACK	
Odometer	378135 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	185/60R15	KAPSEN	9	
L/H Front Tyre	185/60R15	KAPSEN	9	
R/H Rear Tyre	185/60R15	KAPSEN	9	
L/H Rear Tyre	185/60R15	KAPSEN	9	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/09/2024	Inspection Date	16/09/2024	
Survey held at	MASSIVE TRADING & AUTO - BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				