

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Reg. No. 13300713010 GG1 Reg. No. 13 300713010 | | | | | |
|---|---|---|-----------------|--------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | Ref: | CS/AGI24090281/Anp3m4(N) | |
| | (BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924 | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | Date | 9: 05/02/2025 | |
| | ATTN: JANICE KO | Н | Cod | e: AGI | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SMJ 2204J | Veh. Inspected | SMM 3881G | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | C10031678/JK | Excess (\$) | 0.00 | |
| | Assign From | LAN BOON CHIN | Assign Date | 16/09/2024 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | KIA CERATO | c.c | 1591 | |
| | Engine No. | HIDDEN | Year of Reg. | 2019 | |
| | Chassis No. | KNAF3416MK5045976 | Colour | GREY | |
| | Odometer | 114174 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | . Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 225/40R18 | GOODYEAR | 6 mm | |
| | L/H Front Tyre | 225/40R18 | GOODYEAR | 6 mm | |
| | R/H Rear Tyre | 225/40R18 | GOODYEAR | 6 mm | |
| | L/H Rear Tyre | 225/40R18 | GOODYEAR | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 12/09/2024 | Inspection Date | 16/09/2024 | |
| | Survey held at | KT MOTORWERK | | | |
| | | 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | | Estimate Days of Repair | | | |

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: