

ASSIGNMENT

Front: _____ Date: _____

Estimate: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ vehicle No: _____

at _____ km/s

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: There had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMM38816 Yr Regn: 2018 June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato C.D. 1591

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 114174 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF3416MK-5045976

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: 06 mm Rear: 06 mm

R/Bal. 06 mm L/Bal. 06 mm

L/Bal. 06 mm D.O.A. 16/09/24

D.O.A. 16/09/24

Survey held at KT Motorwerk

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees ops

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Budget Direct

COE Expiry

Estimate given during : Yes (✓)

1st Survey : No (✓)

MV :

PV :

Nett :

686D

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

Report Format:

Report 2 Form / L.P. P. CO

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

VEHICLE REPAIR ESTIMATE

Vehicle Number : SMM3881G

Date : 14.09.2024

Vehicle Model : KIA CERATO K3

Chassis : KNAF3416MK50459
76

Accident Date : 12.09.2024

TP Ins. BUDGET DIRECT

Original Reg Date : 27.06.2019

ESTIMATE

11	1 pc	TAILAMP	698.50	698.50	+
12	1 pc	TAILAMP PANELS	298.70	298.70	+
13	1 pcs	TAILAMP INNER SEALER	35.00	35.00	+
14	1 pcs	REAR BUMPER		985.90	+
15	1 pcs	REAR BUMPER SMART KEY SENSOR		275.30	+
16	1 pcs	REAR LOWER BUMPER		485.80	+
17	2 pcs	REAR BUMPER RETAINERS	158.30	316.60	+
18	1 pcs	REAR BUMPER LOWER COVER	168.20	336.40	+
21	1 pc	REAR BUMPER REINFORCEMENT		627.50	+
22	2 pc	REAR REINFORCEMENT TOP BRACKETS	98.90	197.80	+
23	3 pc	REAR REINFORCEMENT BOTTOM BRACKETS	94.50	283.50	+
24	2 pc	REAR BUMPER SENSORS	285.80	571.60	+
26	1 pc	REAR FENDER		1,425.30	+
26	1 pc	REAR FENDER AIR DUCT RH		185.20	+
27	1 pc	REAR FENDER INNERTRIM	334.60	334.60	+
28	1 pc	REAR FENDER INNERSHIELD	195.80	195.80	+
30	1 pc	END PANEL		495.80	+
31	1 pc	END PANEL TOP GARNISH		214.60	+
32	1 pc	END PANEL SMART KEY ANTENNA(INNER)		266.80	+

subtotal 8,230.70

less 10% 823.07

total 7,407.63

Special Nett

1	1 set	Rear Number Plate with Holder	50.00	+
2	1 set	Tailamps clips	30.00	+
3	1 set	Rear Bumper Diffuser (Speical)	950.00	+
4	1 set	Rear Bumper Side Skirt Lip RH (Speical)	350.00	+
5	1 PC	Rims	950.00	+
6	1 PC	Tyre	280.00	+
7	1 set	Rear fender inner trim clips	30.00	+
8	1 set	Rear fender inner shield clips	30.00	+

9	1 set	Body Panel Joint Sealant <i>HP m</i>		120.00	<i>+</i>
---	-------	--------------------------------------	--	--------	----------

Labour charge

Panel Beating		1,000.00	<i>20</i>
Spray painting		1,000.00	<i>20</i>
Check Wiring on tailamps		120.00	<i>+</i>
Anti rust		180.00	<i>+</i>
4 Wheel Aightment		150.00	<i>+</i>
Remove and install reverse sensor		120.00	<i>50</i>
Remove and install interior upholstery		120.00	<i>+</i>
		\$ 12,887.63	

Adrian Lij
2/s 16/09/24
02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: