



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090285/Avh3m4
75 BRAS BASAH ROAD	Date:	12/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 7421M	Veh. Inspected	SLD 3398U
Policy No.	-	Coverage	0
Claim No.	MT/1295558-001	Excess	\$0.00
Assign From	CHARLOTTE CHEW	Assign Date	17/09/2024

2. Vehicle Details

Make & Model	TOYOTA VELLFIRE	C.C	2494
Engine No.	2ARH706273	Year of Reg.	29/03/2016
Chassis No.	JTNGF3DH908004365	Colour	BLACK
Odometer	319419 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55R18	HABILEAD	6
L/H Front Tyre	235/55R18	HABILEAD	6
R/H Rear Tyre	235/55R18	HABILEAD	6
L/H Rear Tyre	235/55R18	HABILEAD	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/09/2024	Inspection Date	17/09/2024 (15:29)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days