

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL	INSURANCE LTD	Ref:	CS/FCI24090308/Anp3m4	
	16 RAFFLES QUAY		Date:	15/11/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 3398H	Veh. Inspected	SNG 1091C	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24008132MFCT	Excess	\$0.00	
	Assign From	JOANNE	Assign Date	17/09/2024	
2.	2. Vehicle Details				
	Make & Model	HYUNDAI AE IONIQ	c.c	1580	
	Engine No.	G4LENU241037	Year of Reg.	09/07/2022	
	Chassis No.	KMHC851CVNU293429	Colour	GREY	
	Odometer	154801 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	185/65R15	APLUS	6	
	L/H Front Tyre	185/65R15	APLUS	6	
	R/H Rear Tyre	185/65R15	APLUS	6	
	L/H Rear Tyre	185/65R15	APLUS	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date 14/09/2024 Inspection Date 17/09/2024				
	Survey held at	d at A-TEC AUTOMOTIVE PTE LTD - 8 KAKI BUKIT AVENUE 4 #04-20 PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks					
A)DAMAGES CONSISTENT TO ACCIDENT REPORT.					
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5/11/1000 LD / LOCK INC MOTIONS, WE TAVE NOT NOT HORIZON METALLO.					

**Estimate Days of Repair**